

7 Winchester Court Mauldin, SC 29662 864-404-3210 Phone 864-404-3213 Fax

802 E. Martintown Rd. Suite 208 N. Augusta, SC 29841 803-440-2790 Phone

www.apex-ehs.com

SERVICES

Indoor Air Quality

Mold Remediation

Asbestos & Lead

Industrial Hygiene

Worker Health & Safety

Mold Consulting

Moisture Management Plans

Safety Assessment

Environmental Site Assessments

Hazard Communication

Apex Project Number 1123-202

December 19, 2023

Ms. Cindy Herrera
Columbia Housing Authority
1917 Harden Street
Spartanburg, South Carolina 29204

Reference: Asbestos Containing Materials Assessment

Columbia Apartments 2131 Slighs Avenue Columbia, South Carolina

Dear Ms. Herrera:

Apex Environmental Management, Inc. (Apex) has completed an asbestos assessment at the above-referenced property slated for demolition. Included in this report are a summary of our field activities and the results obtained. The objectives of the survey included the following:

- Identification of suspect asbestos-containing material (ACM) in readily observable locations. Limited demolition of building materials was conducted during the assessment.
- Asbestos assessment with sample collection by South Carolina Department of Health and Environmental Control (SC DHEC) licensed asbestos building inspector.
- Suspect ACM analysis by polarized light microscopy (PLM) utilizing EMSL Analytical, a NVLAP certified laboratory, their accreditation number is 200841-0.
- Transmission electron microscopy (TEM) analysis of non-friable organically bound materials suspected to contain asbestos and testing negatively by PLM analysis utilizing EMSL Analytical Inc. (EMSL).

Procedure/Methodology

Apex was requested to perform an asbestos assessment of the Columbia Apartments to identify asbestos-containing materials (ACM) which could be disturbed prior to or during scheduled demolition activities. The National Emission Standard for Hazardous Air Pollutants (NESHAP) requires the identification of friable ACM and non-friable ACM likely to become friable during demolition and/or renovation activities. NESHAP requires that the identified ACM be removed prior to initiating activities likely to disturb the ACM.

As per SC DHEC asbestos regulations, bulk asbestos samples were collected from random locations of homogeneous areas based upon the following criteria:

Apex Project # 1123-202 Columbia Apartments Asbestos Assessment Columbia, South Carolina December 19, 2023

- Thermal Insulation Materials (piping, breeching, boiler insulation, etc.) A minimum of three (3) samples are required. Only patch areas (less than 6 square or linear feet) may have one (1) sample collected.
- Surfacing Materials (plaster, fireproofing, sheetrock and joint compound, etc.) A minimum of seven (7) samples are to be taken for areas greater than 5,000 square feet; five (5) for areas greater than 1,000 square feet, but less than 5,000 square feet; three (3) for areas less than 1,000 square feet.
- Miscellaneous Materials (flooring, adhesives, roofing, floor tiles, etc.) A minimum of three (3) samples are required.
 - If samples of non-friable organically bound (NOB) materials were collected and reported by the laboratory to contain less than 1% asbestos by PLM, these materials were reanalyzed in accordance with SCDHEC requirements for NOB's by transmission electron microscopy (TEM).

The asbestos survey was performed by Mr. Ted Shultz (SC DHEC asbestos inspector license # BI-00971, exp. 02/16/2024) on Novemebr 14, 2023. The survey consisted of observing the accessible areas for the presence of suspect materials which may contain asbestos. The survey involved detecting both friable materials (materials which can be crumbled, pulverized or reduced to a powder by hand pressure when dry) and non-friable materials (materials which pose a hazard when sawn, sanded, drilled or pulverized). Homogeneous materials (based on material type, color, texture, etc.) were identified in various functional spaces during the survey.

In order to determine if the suspect materials observed during the visual survey contained asbestos, representative bulk samples were collected and placed in sealed packages. One hundred eighty-seven (187) bulk samples were collected during the survey and submitted to EMSL Analytical in Pineville, North Carolina for analysis using the EPA recommended method of Polarized Light Microscopy (PLM) coupled with dispersion staining (Method No. EPA 600/M4-82-020, Dec. 1982). EMSL participates in the National Voluntary Laboratory Accreditation Program (NVLAP). Their NVLAP accreditation number is 200841-0. Due to EPA regulations, samples are split into homogeneous layers and each layer is analyzed separately. Four hundred thirteen (413) samples were analyzed due to layering by PLM and positive stop methods.

In accordance with South Carolina Regulation 61-86.1, non-friable organically bound materials that are reported to be non-asbestos containing by PLM analysis must also be analyzed by Transmission Electron Microscopy (TEM). Sixty-one (61) samples were analyzed using TEM.

Results

The EPA defines an asbestos-containing material (ACM) as a material containing greater than 1% asbestos. OSHA defines ACM as a material containing detectable amounts of asbestos. A specific *PLM* and *TEM Data Table* is located in Appendix I of this report and identifies positive materials and designates approximate quantities.

No asbestos containing materials were identified during this assessment.

Apex Project # 1123-202 Columbia Apartments Asbestos Assessment Columbia, South Carolina December 19, 2023

Recommendations and Discussion

No asbestos containing material were identified, therefore no recommendations are provided at this time.

This report summarizes our evaluation of the conditions observed at the site. The findings prepared by Apex are based upon testing performed in the building spaces. Our assessment procedures and recommendations are based on the guidelines presented in EPA, State of South Carolina or OSHA asbestos regulations.

Closing

Apex appreciates the opportunity to provide you with our asbestos consulting services and looks forward to our continued association. If you have any questions about this report or any other industrial hygiene concerns, please contact us at (803) 440-2790.

Sincerely,

Apex Environmental Management, Inc.

Ted Shultz Project Manager

Terman k. Shullt

Rebecca W. Shultz, CIH, CSP President

Appendix I PLM & TEM Data Table

Appendix II Laboratory Analytical Results & Chain of Custody

Appendix III Photographs

APPENDIX I PLM & TEM DATA TABLE

Project Name: Columbia Apartments Asbestos Assessment Sampled By: Ted Shultz

Project Location: 2131 Slighs Avenue Columbia, SC Project Manager: Ted Shultz

Sample No.	Location	Sample Description	Analytical Results	Friable/Non Friable	Condition	Quantity
1	Destinition of A	4 Lavan Ohimula 0				
2	Building 1 Roof	1 Layer Shingle & 4 Layers Felt	PLM & TEM NAD	Non-Friable	Damaged	2,500 SF
3	1,001	4 Layers i en				
4						
5	Exterior	Door & Window Caulk	PLM & TEM NAD	Non-Friable	Good	26 EA
6						
7		Top Toytured Fooring				
8	Unit B Kitchen & Bath	Tan Textured Fooring w/Yellow Mastic	PLM & TEM NAD	Non-Friable Good	200 SF	
9		W/ I cliew Mastic				
10						
11	Unit C HVAC Closet	Grey Flooring w/Mastic	PLM & TEM NAD	Non-Friable	Good	10 SF
12						
13		Brown Marble Pattern Flooring				
14	Unit B Kitchen	w/Mastic	PLM & TEM NAD	Non-Friable	Good	100 SF
15		www.c				
16						
17	Units A, B & C Bathrooms	Tub Surrounds Mastic Only	PLM & TEM NAD	Non-Friable	Good	4 EA
18						
19						
20	Entry Stair Well	Stair Tread Mastic	PLM & TEM NAD	Non-Friable	Good	30 EA
21						

Project Name: Columbia Apartments Asbestos Assessment Sampled By: Ted Shultz

Project Location: 2131 Slighs Avenue Columbia, SC Project Manager: Ted Shultz

Sample No.	Location	Sample Description	Analytical Results	Friable/Non Friable	Condition	Quantity
22						
23						
24	Units A, B, C & D					
25	Walls & Ceilings	Drywall & Joint Compound	PLM NAD	Friable	Damaged	5,600 SF
26	Traile a Cominge					
27						
28						
29						
30						
31	Unite C & D Entry Stair well	Textured Plaster & Drywall				
32	Units C & D Entry Stair well Walls & Ceiling	with No Joint Compound	PLM NAD Friable	Damaged	2,000 SF	
33	Walle & Colling	war ito domit dompound				
34						
35						
36						
37	Building 2 Exterior	Door & Window Caulk	PLM & TEM NAD	Non-Friable	Good	26 EA
38						
39		1 Lover Chingle				
40	Roof	1 Layer Shingle & 3 Layers Felt	PLM & TEM NAD	Non-Friable	Damaged	2,500 SF
41		a o Layoro i cit				
42						
43	Entry Stair Well	Stair Tread Mastic	PLM & TEM NAD	Non-Friable	Good	30 EA
44						
45		Cray Tayturad Floaring				
46	Units E & F Kitchen	Grey Textured Flooring w/Mastic	PLM & TEM NAD	Non-Friable	Good	200 SF
47		w/iviastio				

Project Name: Columbia Apartments Asbestos Assessment Sampled By: Ted Shultz

Project Location: 2131 Slighs Avenue Columbia, SC Project Manager: Ted Shultz

Sample No.	Location	Sample Description	Analytical Results	Friable/Non Friable	Condition	Quantity
48		Grey Textured Flooring				
49	Units G & H Kitchen & Bath	W/Mastic PLM & TEM NAD Non-F	Non-Friable	Good	300 SF	
50						
51						
52						
53	Linita F. F. C. 9 Li Malla 9					
54	Units E, F, G & H Walls & Ceiling	Drywall & Joint Compound	PLM & TEM NAD	Friable	Damaged	5,600 SF
55	Coming					
56						
57						
58						
59						
60	_	T				
61	Entry Stair Well Walls & Upstairs Ceilings	Textured Plaster & Drywall with No Joint Compound	PLM NAD	Friable Damaged	2,000 SF	
62	Opstairs Ceilings	with No 30int Compound				
63						
64						
65		44 01: 4				
66	Building 3 Roof	1 Layer Shingle & 3 Layers Felt	PLM & TEM NAD	Non-Friable	Damaged	2,500 SF
67		α 3 Layers Feit				
68						
69	Exterior	Door & Window Caulk	PLM & TEM NAD	Non-Friable	Good	24 EA
70						
71						
72	Entry Stair Well	Stair Tread Mastic	PLM & TEM NAD	Non-Friable	Good	30 EA
73						

Project Name: Columbia Apartments Asbestos Assessment Sampled By: Ted Shultz

Project Location: 2131 Slighs Avenue Columbia, SC Project Manager: Ted Shultz

Sample No.	Location	Sample Description	Analytical Results	Friable/Non Friable	Condition	Quantity
74	Units I, J, K, & L					
75	Bathrooms	Tub Surrounds Mastic Only	PLM & TEM NAD	Non-Friable	Good	4 EA
76						
77	_	2 Layers vinyl floor				
78	Units K & L Bathrooms	(1 grey, 1 tan) with Mastic	PLM & TEM NAD	Non-Friable	Good	200 SF
79		(g. ey, 1 tan / 11 tan 11 tan 1				
80]	Downstairs Kitchen Vinyl				
81	Unit I & J Kitchen	Flooring Marble Tan & Grey	PLM & TEM NAD	Non-Friable	Good	300 SF
82		w/Mastic				
83						
84						
85	Linita I I V 9 I					
86	Units I, J, K & L Walls & Ceiling	Drywall & Joint Compound	PLM NAD	PLM NAD Friable Damaged	5,600	
87	Walls & Selling					
88						
89						
90						
91						
92		Taytured Diaster & Drawall				
93	Enrty Stairs & Upstairs Ceilings	Textured Plaster & Drywall with No Joint Compound	PLM NAD	Friable	Damaged	2,000 SF
94		With 140 doint Compound				
95	7					
96]					
97		4 Lavan Obia al- 0				
98	Building 4 Roof	1 Layer Shingle & 3 Layers Felt	PLM & TEM NAD	Non-Friable	Damaged	2,500 SF
99]	5 Layers I ell				

Project Name: Columbia Apartments Asbestos Assessment Sampled By: Ted Shultz

Project Location: 2131 Slighs Avenue Columbia, SC Project Manager: Ted Shultz

Sample No.	Location	Sample Description	Analytical Results	Friable/Non Friable	Condition	Quantity
100						
101	Exterior	Door & Window Caulk	PLM & TEM NAD	Non-Friable	Good	24 EA
102						
103	Units A, B, C & D					
104	Entry Stairs	Stair Tread Mastic	PLM & TEM NAD	Non-Friable	Good	30 EA
105	2.1, 3.3					
106	Units A, B, C & D	Bathtub Surround				
107	Bathrooms	Mastic Only	PLM & TEM NAD	Non-Friable	Good	4 EA
108	Baunceme	Madae Omy				
109	Lipito A. P. C. 9. D.					
110	Units A, B, C & D Bathrooms & Kitchens	Marbled Vinyl w/ Mastic	PLM & TEM NAD	Non-Friable	Good	300 SF
111	Battiloonio a ratoriorio					
112						
113						
114	Linita A. D. C. S. D.					
115	Units A, B, C, & D Walls & Ceilings	Drywall & Joint Compound	PLM NAD	Friable	Damaged	5,600 SF
116	Walla & Jellings					
117						
118						
119						
120						
121	Units C & D Entry Stair well Walls & Ceiling	Tanking d Diaster 9 Desert !!				
122		Textured Plaster & Drywall with No Joint Compound	PLM NAD	Friable	Damaged	2,000 SF
123	vvalis & Celling	with two doint Compound				
124						
125						

Project Name: Columbia Apartments Asbestos Assessment Sampled By: Ted Shultz

Project Location: 2131 Slighs Avenue Columbia, SC Project Manager: Ted Shultz

Sample No.	Location	Sample Description	Analytical Results	Friable/Non Friable	Condition	Quantity
126		1 Lover Chingle 9				
127	Building 5 Roof	1 Layer Shingle & 3 Layers Felt	PLM & TEM NAD	Non-Friable	Damaged	2,500 SF
128		o Layers i en				
129						
130	Exterior	Door & Window Caulk	PLM & TEM NAD	Non-Friable	Good	24 EA
131						
132						
133	Entry Stair Well	Stair Tread Mastic	PLM & TEM NAD	Non-Friable	Non-Friable Good	30 EA
134						
135	11mits F F C 0 11					
136	Units E, F, G & H Bathrooms	Tub Surrounds Mastic Only	PLM & TEM NAD	Non-Friable	Good	4 EA
137	Datillooms					
138		Markle Testure d Dettern Viscol				
139	Units E, F, G & H Kitchen & Bathrooms	Marble Textured Pattern Vinyl Flooring w/Mastic	PLM & TEM NAD	Non-Friable	Good	300 SF
140	Datillooms	1 looning w/iviastic				
141						
142						
143	11					
144	Units E, F, G & H Walls & Ceiling	Drywall & Joint Compound	PLM NAD	Friable	Damaged	5,600 SF
145	vvalis & Celling					
146						
147						

Project Name: Columbia Apartments Asbestos Assessment Sampled By: Ted Shultz

Project Location: 2131 Slighs Avenue Columbia, SC Project Manager: Ted Shultz

Sample No.	Location	Sample Description	Analytical Results	Friable/Non Friable	Condition	Quantity
148						
149						
150	Units E & H Walls & Entry	Textured Plaster & Drywall				
151	Stairwells	with No Joint Compound	PLM NAD	Friable	Damaged	2,000 SF
152	Giaii Welle	Will He come compound				
153						
154						
155		1 Lover Chingle 9				
156	Building 6 Roof	1 Layer Shingle & 2 Layers Felt	PLM & TEM NAD	Non-Friable	Damaged	2,500 SF
157		2 Layers i en				
158						
159	Exterior	Door & Window Caulk	PLM & TEM NAD	Non-Friable	Good	24 EA
160						
161						
162	Entry Stairwell	Stair Tread Mastic	PLM & TEM NAD	Non-Friable	Good	30 EA
163						
164	Linite A. D. C. 9. D.	Mankle Testumed Dettems Viscol				
165	Units A, B, C & D Kitchens	Marble Textured Pattern Vinyl Flooring w/Mastic	PLM & TEM NAD	Non-Friable	Good	300 SF
166	Tatonons	1 looming wividedio				
167						
168						
169	Linita A D C 9 D					
170	Units A, B, C & D Walls and Ceilings	Drywall & Joint Compound	PLM NAD	Friable	Damaged	5,600 SF
171	vvalis and Cellings					
172						
173						

Project Name: Columbia Apartments Asbestos Assessment Sampled By: Ted Shultz

Project Location: 2131 Slighs Avenue Columbia, SC Project Manager: Ted Shultz

Project Number: 1123-202 Date: 11/14/2023

Sample No.	Location	Sample Description	Analytical Results	Friable/Non Friable	Condition	Quantity
174						
175						
176	Linita C. 9. D. Entmy Stain well	Taxtured Diaster 9 Dwgwell			Damaged	
177	Units C & D Entry Stair well Walls & Ceiling	Textured Plaster & Drywall with No Joint Compound	PLM NAD	Non-Friable	Damaged	2,000 SF
178	vvalis & celling	With No doint Compound				
179						
180						
181						
182						
183						
184	Laundry Shed	Drywall & Joint Compound	PLM NAD	Non-Friable	Good	1,300 SF
185						
186						
187						

NAD = No Asbestos Detected

LF = Linear Feet

EA = Each

Bold = Positive For Asbestos

SF = Square Feet

APPENDIX II LABORATORY ANALYTICAL RESULTS & CHAIN OF CUSTODY



7 Winchester Court

Mauldin, SC 29662

Apex Environmental Management

EMSL Order: 412313753 Customer ID: AXEM25

Customer PO: Project ID:

Phone: (803) 348-4921

Fax:

Received Date: 11/16/2023 9:20 AM
Analysis Date: 11/16/2023 - 11/21/2023

Collected Date: 11/14/2023

Project: CHA ACM Cola Apts

Attention: Ted Shultz

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

			Non-Asbe	stos	<u>Asbestos</u>	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
1-Shingle	Build. 1 - Roof - 1 Shingle, 4 Felt	Brown/Black Fibrous Heterogeneous	12% Glass	4% Quartz 15% Ca Carbonate 69% Non-fibrous (Other)	None Detected	
1-Black Felt 1	Build. 1 - Roof - 1 Shingle, 4 Felt	Black Fibrous	75% Cellulose <1% Glass	<1% Quartz 25% Non-fibrous (Other)	None Detected	
412313753-0001A		Homogeneous				
1-Black Felt 2	Build. 1 - Roof - 1 Shingle, 4 Felt	Black Fibrous	75% Cellulose <1% Glass	<1% Quartz 25% Non-fibrous (Other)	None Detected	
412313753-0001B	Della Desta	Homogeneous	000/ 0 - 11 - 1	00/ No. (011 - 1)	N D. t t. I	
1-Tan Felt 412313753-0001C	Build. 1 - Roof - 1 Shingle, 4 Felt	Tan Fibrous	90% Cellulose 2% Glass	8% Non-fibrous (Other)	None Detected	
	Duild 4 Deef 4	Homogeneous	750/ O-III-I	20/ 0	Nama Datastad	
1-Black Felt 3 412313753-0001D	Build. 1 - Roof - 1 Shingle, 4 Felt	Black Fibrous Homogeneous	75% Cellulose <1% Glass	2% Quartz 23% Non-fibrous (Other)	None Detected	
2-Shingle	Build. 1 - Roof - 1 Shingle, 4 Felt	Brown/Black Fibrous	15% Glass	10% Quartz 15% Ca Carbonate	None Detected	
412313753-0002	J ,	Heterogeneous		60% Non-fibrous (Other)		
Result includes a small amo	unt of inseparable attached tar.					
2-Black Felt 1	Build. 1 - Roof - 1 Shingle, 4 Felt	Black Fibrous	80% Cellulose	20% Non-fibrous (Other)	None Detected	
412313753-0002A		Homogeneous				
2-Black Felt 2	Build. 1 - Roof - 1 Shingle, 4 Felt	Black Fibrous	80% Cellulose	20% Non-fibrous (Other)	None Detected	
412313753-0002B		Homogeneous				
2-Tan Felt	Build. 1 - Roof - 1 Shingle, 4 Felt	Tan Fibrous	95% Cellulose	5% Non-fibrous (Other)	None Detected	
412313753-0002C		Homogeneous				
2-Black Felt 3	Build. 1 - Roof - 1 Shingle, 4 Felt	Black Fibrous	80% Cellulose	20% Non-fibrous (Other)	None Detected	
412313753-0002D		Homogeneous				
4-Caulk 412313753-0003	Build. 1 - Exterior - Door & Window Caulk	Gray/White Non-Fibrous Homogeneous		<1% Quartz 100% Non-fibrous (Other)	None Detected	
4-Brick	Build. 1 - Exterior -	Red		8% Quartz	None Detected	
4-Brick 412313753-0003A	Door & Window Caulk	Non-Fibrous Homogeneous		92% Non-fibrous (Other)	Notic Detected	
5	Build. 1 - Exterior - Door & Window Caulk	White/Red Non-Fibrous		2% Quartz 98% Non-fibrous (Other)	None Detected	
412313753-0004 Result includes a small amo	unt of inseparable attached brick	Heterogeneous		constitution (outer)		
7-Tan Mastic/Leveler	Build. 1 - B-Kitchen & Bath - Tan Textured	Gray/Tan Non-Fibrous	3% Glass	8% Quartz 10% Ca Carbonate	None Detected	
412313753-0005	Flooring & Yellow Mastic	Heterogeneous		79% Non-fibrous (Other)		
7-Flooring	Build. 1 - B-Kitchen & Bath - Tan Textured	Tan Fibrous	12% Cellulose 8% Synthetic	20% Ca Carbonate 60% Non-fibrous (Other)	None Detected	
412313753-0005A	Flooring & Yellow Mastic	Heterogeneous	•	,		



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

			Non-Asbe	stos	<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
7-Yellow Mastic	Build. 1 - B-Kitchen & Bath - Tan Textured Flooring & Yellow Mastic	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
7-Leveler	Build. 1 - B-Kitchen &	Brown/Gray	2% Cellulose	6% Quartz	None Detected
412313753-0005C	Bath - Tan Textured Flooring & Yellow Mastic	Non-Fibrous Homogeneous		50% Ca Carbonate 42% Non-fibrous (Other)	
8-Tan Mastic/Leveler	Build. 1 - B-Kitchen & Bath - Tan Textured	Gray/Tan Non-Fibrous		5% Quartz 95% Non-fibrous (Other)	None Detected
412313753-0006	Flooring & Yellow Mastic	Heterogeneous		93 % Noti-fibrous (Other)	
8-Flooring	Build. 1 - B-Kitchen & Bath - Tan Textured	Gray/Tan/White Non-Fibrous	<1% Synthetic 2% Glass	20% Ca Carbonate 78% Non-fibrous (Other)	None Detected
412313753-0006A	Flooring & Yellow Mastic	Homogeneous	270 Glass	76% Noti-librous (Other)	
8-Yellow Mastic	Build. 1 - B-Kitchen &	Yellow	<1% Cellulose	100% Non-fibrous (Other)	None Detected
412313753-0006B	Bath - Tan Textured Flooring & Yellow Mastic	Non-Fibrous Homogeneous			
8-Leveler	Build. 1 - B-Kitchen &	White		15% Quartz	None Detected
412313753-0006C	Bath - Tan Textured Flooring & Yellow Mastic	Non-Fibrous Homogeneous		85% Non-fibrous (Other)	
10-Flooring	Building 1 - C HVAC Closet - Grey Flooring	Gray/Beige Non-Fibrous	2% Cellulose	20% Ca Carbonate 3% Mica	None Detected
412313753-0007	w/ Mastic Building 1 - C HVAC	Heterogeneous Tan	<1% Cellulose	75% Non-fibrous (Other) 2% Quartz	None Detected
10-Mastic 412313753-0007A	Closet - Grey Flooring w/ Mastic	Non-Fibrous Homogeneous	176 Cellulose	<1% Ca Carbonate 98% Non-fibrous (Other)	None Detected
11-Flooring	Building 1 - C HVAC	Gray/Beige	5% Cellulose	15% Ca Carbonate	None Detected
412313753-0008	Closet - Grey Flooring w/ Mastic	Fibrous Heterogeneous		80% Non-fibrous (Other)	
11-Mastic	Building 1 - C HVAC Closet - Grey Flooring	Tan Non-Fibrous		2% Quartz 98% Non-fibrous (Other)	None Detected
412313753-0008A	w/ Mastic	Homogeneous		90 % Non-librous (Other)	
13-Flooring	Building 1 - B Kitchen	Brown	15% Synthetic	20% Ca Carbonate	None Detected
412313753-0009	- Brown Marble Pattern Flooring w/ Mastic	Fibrous Heterogeneous	10% Glass	55% Non-fibrous (Other)	
13-Mastic	Building 1 - B Kitchen	Yellow		<1% Ca Carbonate	None Detected
412313753-0009A	- Brown Marble Pattern Flooring w/ Mastic	Non-Fibrous Homogeneous		100% Non-fibrous (Other)	
13-Leveler	Building 1 - B Kitchen	Gray Non Fibrous	2% Cellulose	40% Ca Carbonate	None Detected
412313753-0009B	- Brown Marble Pattern Flooring w/ Mastic	Non-Fibrous Homogeneous		58% Non-fibrous (Other)	
14	Building 1 - B Kitchen - Brown Marble	Gray/White Non-Fibrous	5% Glass	20% Ca Carbonate 75% Non-fibrous (Other)	None Detected
412313753-0010	Pattern Flooring w/ Mastic	Homogeneous		7370 Noti-fibious (Other)	
16-Paneling	Building 1 - A, B, C, D Bathroom - Tub	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
412313753-0011	Surround Mastic	Homogeneous			
16-Mastic	Building 1 - A, B, C, D Bathroom - Tub	Tan Non-Fibrous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
412313753-0011A	Surround Mastic	Homogeneous			



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

		Non-J		<u>stos</u>	<u>Asbestos</u>	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
17-Paneling	Building 1 - A, B, C, D Bathroom - Tub Surround Mastic	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected	
17-Mastic 412313753-0012A	Building 1 - A, B, C, D Bathroom - Tub Surround Mastic	Yellow Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected	
18-Paneling	Building 1 - A, B, C, D Bathroom - Tub	White Non-Fibrous		10% Ca Carbonate 90% Non-fibrous (Other)	None Detected	
112313753-0012B 19	Surround Mastic Building 1 - Entry Stairwell - Stair Tread	Homogeneous Tan Non-Fibrous	<1% Glass	15% Ca Carbonate 85% Non-fibrous (Other)	None Detected	
412313753-0013	Mastic	Homogeneous				
20 412313753-0014	Building 1 - Entry Stairwell - Stair Tread Mastic	Beige Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected	
22-Joint Compound	Building 1 - A, B, C, D Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		70% Ca Carbonate 3% Perlite 27% Non-fibrous (Other)	None Detected	
22-Drywall 412313753-0015A	Building 1 - A, B, C, D Walls & Ceiling - Drywall & JC	Gray Non-Fibrous Homogeneous	6% Cellulose	94% Non-fibrous (Other)	None Detected	
23-Joint Compound	Building 1 - A, B, C, D Walls & Ceiling -	White Non-Fibrous		70% Ca Carbonate 5% Perlite	None Detected	
23-Drywall	Drywall & JC Building 1 - A, B, C, D Walls & Ceiling -	Homogeneous Gray Non-Fibrous	8% Cellulose	25% Non-fibrous (Other) 92% Non-fibrous (Other)	None Detected	
412313753-0016A	Drywall & JC	Homogeneous				
24-Joint Compound	Building 1 - A, B, C, D Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		70% Ca Carbonate 4% Perlite 26% Non-fibrous (Other)	None Detected	
24-Drywall	Building 1 - A, B, C, D Walls & Ceiling -	Gray Non-Fibrous	6% Cellulose	94% Non-fibrous (Other)	None Detected	
412313753-0017A	Drywall & JC	Homogeneous				
25-Joint Compound	Building 1 - A, B, C, D Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		70% Ca Carbonate 3% Perlite 27% Non-fibrous (Other)	None Detected	
25-Drywall	Building 1 - A, B, C, D Walls & Ceiling -	Gray Non-Fibrous	8% Cellulose	92% Non-fibrous (Other)	None Detected	
412313753-0018A	Drywall & JC	Homogeneous				
26-Joint Compound	Building 1 - A, B, C, D Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		70% Ca Carbonate 30% Non-fibrous (Other)	None Detected	
26-Drywall	Building 1 - A, B, C, D Walls & Ceiling -	Gray Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected	
412313753-0019A	Drywall & JC	Homogeneous				
27-Joint Compound	Building 1 - A, B, C, D Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		70% Ca Carbonate 30% Non-fibrous (Other)	None Detected	
27-Drywall	Building 1 - A, B, C, D Walls & Ceiling -	Gray Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected	
412313753-0020A	Drywall & JC	Homogeneous				
28-Joint Compound	Building 1 - A, B, C, D Walls & Ceiling -	White Non-Fibrous		70% Ca Carbonate 30% Non-fibrous (Other)	None Detected	
<u>412313753-0021</u> 28-Drywall	Drywall & JC Building 1 - A, B, C, D Walls & Ceiling -	Homogeneous Gray Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected	
412313753-0021A	Drywall & JC	Homogeneous				



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

			Non-Asbe	<u>stos</u>	Asbestos		
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type		
29-Tan Coat 412313753-0022	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		55% Quartz 20% Ca Carbonate 25% Non-fibrous (Other)	None Detected		
29-Gray Coat 412313753-0022A	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		60% Quartz 40% Non-fibrous (Other)	None Detected		
29-Drywall 412313753-0022B	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected		
30-Tan Coat 412313753-0023	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		50% Quartz 20% Ca Carbonate 30% Non-fibrous (Other)	None Detected		
30-Gray Coat 412313753-0023A	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		60% Quartz 40% Non-fibrous (Other)	None Detected		
30-Drywall 412313753-0023B	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	6% Cellulose	94% Non-fibrous (Other)	None Detected		
31-Tan Coat 412313753-0024	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		50% Quartz 20% Ca Carbonate 30% Non-fibrous (Other)	None Detected		
31-Gray Coat 412313753-0024A	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		60% Quartz 40% Non-fibrous (Other)	None Detected		
31-Drywall 412313753-0024B	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected		
32-Tan Coat 412313753-0025	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		50% Quartz 20% Ca Carbonate 30% Non-fibrous (Other)	None Detected		
32-Gray Coat 412313753-0025A	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		60% Quartz 40% Non-fibrous (Other)	None Detected		
32-Drywall 412313753-0025B	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	8% Cellulose	92% Non-fibrous (Other)	None Detected		



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

		Non-Asbestos			<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
33-Tan Coat 412313753-0026	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		40% Quartz 15% Ca Carbonate 45% Non-fibrous (Other)	None Detected
No drywall present.					
34-Tan Coat 412313753-0027	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		40% Quartz 15% Ca Carbonate 45% Non-fibrous (Other)	None Detected
No drywall present.					
34-Gray Coat 412313753-0027A	Building 1 - C & D Ceiling & Entry Stairwell Walls -	Gray Non-Fibrous Homogeneous		60% Quartz 40% Non-fibrous (Other)	None Detected
	Textured Plaster & Drywall w/ No JC				
35-Tan Coat 412313753-0028	Building 1 - C & D Ceiling & Entry Stairwell Walls - Textured Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		40% Quartz 15% Ca Carbonate 45% Non-fibrous (Other)	None Detected
No drywall present.					
36	Build. 2 - Exterior - Door & Window Caulk	White Non-Fibrous		100% Non-fibrous (Other)	None Detected
412313753-0029 37	Build. 2 - Exterior -	Homogeneous Gray/White		2% Ca Carbonate	None Detected
412313753-0030	Door & Window Caulk	Non-Fibrous Homogeneous		98% Non-fibrous (Other)	None Detected
39-Shingle	Build. 2 - Roof - 1 Shingle, 3 Felt	Brown/Gray/Black Fibrous Heterogeneous	15% Glass	5% Quartz 15% Ca Carbonate 65% Non-fibrous (Other)	None Detected
39-Felt 1	Build. 2 - Roof - 1	Brown/Black	80% Cellulose	20% Non-fibrous (Other)	None Detected
412313753-0031A	Shingle, 3 Felt	Fibrous Homogeneous	<1% Glass	2070 11011 1121000 (0 11101)	
39-Felt 2	Build. 2 - Roof - 1 Shingle, 3 Felt	Brown/Black Fibrous	80% Cellulose <1% Glass	20% Non-fibrous (Other)	None Detected
412313753-0031B		Homogeneous			
39-Felt 3 412313753-0031C	Build. 2 - Roof - 1 Shingle, 3 Felt	Brown/Black Fibrous	80% Cellulose <1% Glass	20% Non-fibrous (Other)	None Detected
40-Shingle	Build. 2 - Roof - 1 Shingle, 3 Felt	Homogeneous Gray/Black Fibrous	10% Glass	2% Quartz 20% Ca Carbonate	None Detected
412313753-0032		Homogeneous		68% Non-fibrous (Other)	
40-Felt 1	Build. 2 - Roof - 1 Shingle, 3 Felt	Black Fibrous	90% Cellulose	10% Non-fibrous (Other)	None Detected
412313753-0032A		Homogeneous			
40-Felt 2 412313753-0032B	Build. 2 - Roof - 1 Shingle, 3 Felt	Black Fibrous	90% Cellulose 2% Glass	8% Non-fibrous (Other)	None Detected
40-Felt 3	Build. 2 - Roof - 1	Homogeneous Black	90% Cellulose	10% Non-fibrous (Other)	None Detected
40-Feit 3 412313753-0032C	Shingle, 3 Felt	Fibrous Homogeneous	30 /0 Cellulose	10 /0 NOIT-IIDIOUS (Other)	None Detected
42	Build. 2 - Entry Stairs - Stair Tread Mastic	Brown/Tan Non-Fibrous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
412313753-0033		Homogeneous		· ,	



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

		Non-Asbestos			<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
43 412313753-0034	Build. 2 - Entry Stairs - Stair Tread Mastic	Brown/Red/Yellow Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (Other)	None Detected
45-Flooring	Build. 2 - E & F Kitchen - Grey Text	Gray/Tan Non-Fibrous	8% Synthetic 10% Glass	20% Ca Carbonate 62% Non-fibrous (Other)	None Detected
412313753-0035	Floor w/ Mastic	Homogeneous	1070 Glass	02 % Non-librous (Other)	
45-Mastic/Leveler	Build. 2 - E & F Kitchen - Grey Text	Gray/Tan/Yellow Non-Fibrous	3% Cellulose	10% Ca Carbonate 87% Non-fibrous (Other)	None Detected
412313753-0035A	Floor w/ Mastic	Heterogeneous			
16-Flooring	Build. 2 - E & F Kitchen - Grey Text	Gray/White Fibrous	<1% Synthetic 5% Glass	20% Ca Carbonate 75% Non-fibrous (Other)	None Detected
412313753-0036	Floor w/ Mastic	Homogeneous			
46-Mastic/Leveler	Build. 2 - E & F Kitchen - Grey Text Floor w/ Mastic	Gray/Yellow Non-Fibrous	2% Cellulose	5% Ca Carbonate 93% Non-fibrous (Other)	None Detected
412313753-0036A		Heterogeneous	20/ 2	000/ 0 0 1 1	
48-Flooring 412313753-0037	Build. 2 - G & H Kit & Bath - Grey Text Floor w/ Mastic	Gray/Tan Non-Fibrous Homogeneous	6% Synthetic 10% Glass	20% Ca Carbonate 64% Non-fibrous (Other)	None Detected
48-Mastic	Build. 2 - G & H Kit &	Yellow	<1% Cellulose	100% Non-fibrous (Other)	None Detected
48-Mastic 412313753-0037A	Bath - Grey Text Floor w/ Mastic	Non-Fibrous Homogeneous	- 170 OchulOSE	100 % Noti-fibrous (Other)	HONE DELECTED
49-Flooring	Build, 2 - G & H Kit &	Gray	2% Synthetic	20% Ca Carbonate	None Detected
112313753-0038	Bath - Grey Text Floor w/ Mastic	Non-Fibrous Homogeneous	273 Oynunduo	78% Non-fibrous (Other)	None Detected
l9-Mastic	Build. 2 - G & H Kit &	Yellow		100% Non-fibrous (Other)	None Detected
112313753-0038A	Bath - Grey Text Floor w/ Mastic	Non-Fibrous Homogeneous		100 / Non-librous (Other)	None Detected
51-Tape	Build. 2 - E, F, G, H	White	40% Synthetic	5% Non-fibrous (Other)	None Detected
71 1490	Walls & Ceiling -	Fibrous	55% Glass	2.2	
12313753-0039	Drywall & JC	Homogeneous			
1-Joint Compound	Build. 2 - E, F, G, H	White		80% Ca Carbonate	None Detected
112313753-0039A	Walls & Ceiling - Drywall & JC	Non-Fibrous		4% Perlite	
		Homogeneous White	100/ Callulana	16% Non-fibrous (Other)	Nana Datastad
51-Drywall	Build. 2 - E, F, G, H Walls & Ceiling -	Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
112313753-0039B	Drywall & JC	Homogeneous			
52-Tape	Build. 2 - E, F, G, H	White	40% Synthetic	5% Non-fibrous (Other)	None Detected
•	Walls & Ceiling -	Fibrous	55% Glass	,	
412313753-0040	Drywall & JC	Homogeneous			
52-Joint Compound	Build. 2 - E, F, G, H Walls & Ceiling -	White Non-Fibrous		80% Ca Carbonate 4% Perlite	None Detected
412313753-0040A	Drywall & JC	Homogeneous		16% Non-fibrous (Other)	
52-Drywall	Build. 2 - E, F, G, H Walls & Ceiling -	Tan/White Non-Fibrous	5% Cellulose	95% Non-fibrous (Other)	None Detected
412313753-0040B	Drywall & JC	Homogeneous			
53-Tape	Build. 2 - E, F, G, H Walls & Ceiling -	White Fibrous Homogeneous	40% Synthetic 55% Glass	5% Non-fibrous (Other)	None Detected
412313753-0041	Drywall & JC	-		900/ C- C	News Date to 1
53-Joint Compound	Build. 2 - E, F, G, H Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 4% Perlite 16% Non-fibrous (Other)	None Detected
		-	30/ Callulana	,	None Detected
53-Drywall 412313753-0041B	Build. 2 - E, F, G, H Walls & Ceiling - Drywall & JC	Tan/White Non-Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
54-Joint Compound	Build. 2 - E, F, G, H	White		80% Ca Carbonate	None Detected
·	Walls & Ceiling -	Non-Fibrous		4% Perlite	
412313753-0042	Drywall & JC	Homogeneous		16% Non-fibrous (Other)	



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample			<u>Asbestos</u>		
	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
54-Drywall 412313753-0042A	Build. 2 - E, F, G, H Walls & Ceiling - Drywall & JC	Tan/White Non-Fibrous Homogeneous	4% Cellulose	96% Non-fibrous (Other)	None Detected
55-Joint Compound	Build. 2 - E, F, G, H Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
55-Drywall 412313753-0043A	Build. 2 - E, F, G, H Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous	10% Cellulose <1% Glass	90% Non-fibrous (Other)	None Detected
56-Joint Compound	Build. 2 - E, F, G, H Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
56-Drywall 412313753-0044A	Build. 2 - E, F, G, H Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous	10% Cellulose <1% Glass	90% Non-fibrous (Other)	None Detected
57-Tape	Build. 2 - E, F, G, H Walls & Ceiling -	White Fibrous	10% Synthetic 80% Glass	10% Non-fibrous (Other)	None Detected
412313753-0045 57-Joint Compound 412313753-0045A	Drywall & JC Build. 2 - E, F, G, H Walls & Ceiling - Drywall & JC	Homogeneous White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
57-Drywall	Build. 2 - E, F, G, H Walls & Ceiling -	White Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
412313753-0045B 58-Tan Coat	Drywall & JC Build. 2 - Upstairs	Homogeneous Tan		60% Quartz	None Detected
412313753-0046	Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Non-Fibrous Homogeneous		15% Ca Carbonate 25% Non-fibrous (Other)	
58-Gray Coat 412313753-0046A	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		60% Quartz 40% Non-fibrous (Other)	None Detected
58-Drywall 412313753-0046B	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
59-Tan Coat 412313753-0047	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		60% Quartz 15% Ca Carbonate 25% Non-fibrous (Other)	None Detected
59-Gray Coat 412313753-0047A	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		60% Quartz 40% Non-fibrous (Other)	None Detected
59-Drywall 412313753-0047B	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	6% Cellulose	94% Non-fibrous (Other)	None Detected
60-Tan Coat 412313753-0048	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		60% Quartz 15% Ca Carbonate 25% Non-fibrous (Other)	None Detected



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	<u>Non-Asbestos</u>			<u>Asbestos</u>
		Appearance	% Fibrous	% Non-Fibrous	% Type
60-Gray Coat 412313753-0048A	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		60% Quartz 40% Non-fibrous (Other)	None Detected
60-Drywall 412313753-0048B	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	8% Cellulose	92% Non-fibrous (Other)	None Detected
61-Tan Coat 412313753-0049	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		60% Quartz 15% Ca Carbonate 25% Non-fibrous (Other)	None Detected
61-Gray Coat 412313753-0049A	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		60% Quartz 40% Non-fibrous (Other)	None Detected
61-Drywall 412313753-0049B	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
61-Insulation 412313753-0049C	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	White Fibrous Homogeneous	90% Glass	10% Non-fibrous (Other)	None Detected
62-Tan Coat 412313753-0050	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Tan/White Non-Fibrous Homogeneous		30% Quartz 5% Ca Carbonate 65% Non-fibrous (Other)	None Detected
62-Gray Coat 412313753-0050A	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		40% Quartz 60% Non-fibrous (Other)	None Detected
62-Drywall 412313753-0050B	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	10% Cellulose <1% Glass	90% Non-fibrous (Other)	None Detected
62-Insulation 412313753-0050C	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Yellow Fibrous Homogeneous	99% Glass	1% Non-fibrous (Other)	None Detected
63-Tan Coat 412313753-0051	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Tan/White Non-Fibrous Homogeneous		30% Quartz 5% Ca Carbonate 65% Non-fibrous (Other)	None Detected
63-Gray Coat 412313753-0051A	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		40% Quartz 60% Non-fibrous (Other)	None Detected



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Non-Asbestos			Asbestos	
		Appearance	% Fibrous	% Non-Fibrous	% Type	
63-Drywall 412313753-0051B	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected	
64-Tan Coat 412313753-0052	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Tan/White Non-Fibrous Homogeneous		30% Quartz 10% Ca Carbonate 60% Non-fibrous (Other)	None Detected	
64-Gray Coat 412313753-0052A	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		40% Quartz 60% Non-fibrous (Other)	None Detected	
64-Gray Drywall 412313753-0052B	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	5% Cellulose <1% Glass	95% Non-fibrous (Other)	None Detected	
64-White Drywall	Build. 2 - Upstairs Ceilings & Entry Stairs Walls - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected	
65-Shingle	Build 3 - Roof - 1 Shingle, 3 Felt	Gray/Black Non-Fibrous Heterogeneous	15% Glass	5% Quartz 15% Ca Carbonate 65% Non-fibrous (Other)	None Detected	
65-Felt 1	Build 3 - Roof - 1 Shingle, 3 Felt	Brown/Black Fibrous Homogeneous	75% Cellulose <1% Glass	25% Non-fibrous (Other)	None Detected	
65-Felt 2	Build 3 - Roof - 1 Shingle, 3 Felt	Brown/Black Fibrous Homogeneous	80% Cellulose <1% Glass	20% Non-fibrous (Other)	None Detected	
65-Felt 3	Build 3 - Roof - 1 Shingle, 3 Felt	Brown/Black Fibrous Homogeneous	80% Cellulose <1% Glass	20% Non-fibrous (Other)	None Detected	
65-Insulation	Build 3 - Roof - 1 Shingle, 3 Felt	Brown Fibrous Homogeneous	95% Glass	5% Non-fibrous (Other)	None Detected	
66-Shingle	Build 3 - Roof - 1 Shingle, 3 Felt	Gray/Black Fibrous Homogeneous	10% Glass	2% Quartz 20% Ca Carbonate 68% Non-fibrous (Other)	None Detected	
66-Felt 1	Build 3 - Roof - 1 Shingle, 3 Felt	Black Fibrous	90% Cellulose	10% Non-fibrous (Other)	None Detected	
66-Felt 2	Build 3 - Roof - 1 Shingle, 3 Felt	Homogeneous Black Fibrous	90% Cellulose	10% Non-fibrous (Other)	None Detected	
412313753-0054B 66-Felt 3	Build 3 - Roof - 1 Shingle, 3 Felt	Homogeneous Black Fibrous	90% Cellulose	10% Non-fibrous (Other)	None Detected	
412313753-0054C 66-Insulation 412313753-0054D	Build 3 - Roof - 1 Shingle, 3 Felt	Homogeneous Brown/Yellow Fibrous Homogeneous	99% Glass	1% Non-fibrous (Other)	None Detected	
67-Insulation	Build 3 - Roof - 1 Shingle, 3 Felt	Yellow Fibrous	99% Glass	1% Non-fibrous (Other)	None Detected	
412313753-0054E		Homogeneous				



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

	Description	Non-Asbestos			Asbestos % Type	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
68 412313753-0055	Build 3 - Exterior - Door & Window Caulk	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected	
69	Build 3 - Exterior - Door & Window Caulk	White/Red Non-Fibrous	<1% Cellulose	2% Ca Carbonate 98% Non-fibrous (Other)	None Detected	
412313753-0056 71	Build 3 - Entry Stairs - Stair Tread Mastic	Homogeneous Brown/White Non-Fibrous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected	
412313753-0057		Homogeneous				
72	Build 3 - Entry Stairs - Stair Tread Mastic	Tan/Yellow Non-Fibrous	<1% Cellulose	100% Non-fibrous (Other)	None Detected	
412313753-0058		Homogeneous				
74 412313753-0059	Build 3 - I, J, K, L Bathrooms - Tub Surround Mastic Only	Tan Non-Fibrous Homogeneous		10% Ca Carbonate 90% Non-fibrous (Other)	None Detected	
				100% Non fibrous (Other)	None Detected	
75 412313753-0060	Build 3 - I, J, K, L Bathrooms - Tub Surround Mastic Only	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected	
77-Gray Flooring	Build 3 - K & L	Gray	15% Cellulose	20% Ca Carbonate	None Detected	
412313753-0061	Bathroom Floor, 2 Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Fibrous Homogeneous	4% Glass	61% Non-fibrous (Other)	=	
77-Mastic	Build 3 - K & L Bathroom Floor, 2	Tan Non-Fibrous	2% Cellulose <1% Synthetic	<1% Ca Carbonate 98% Non-fibrous (Other)	None Detected	
412313753-0061A	Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Homogeneous	<1% Glass			
77-Tan Flooring	Build 3 - K & L Bathroom Floor, 2	Tan Fibrous	6% Synthetic 10% Glass	20% Ca Carbonate 64% Non-fibrous (Other)	None Detected	
412313753-0061B	Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Heterogeneous		, ,		
77-Mastic	Build 3 - K & L Bathroom Floor, 2	Yellow Non-Fibrous		<1% Ca Carbonate 100% Non-fibrous (Other)	None Detected	
412313753-0061C	Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Homogeneous		100 % Nor IIID odd (Odior)		
77-Leveler	Build 3 - K & L Bathroom Floor, 2	Gray Non-Fibrous	2% Cellulose	4% Quartz 40% Ca Carbonate	None Detected	
412313753-0061D	Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Homogeneous		54% Non-fibrous (Other)		
78-Gray Flooring	Build 3 - K & L Bathroom Floor, 2	Gray Fibrous	15% Cellulose	85% Non-fibrous (Other)	None Detected	
412313753-0062	Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Homogeneous				
78-Mastic	Build 3 - K & L	Yellow		100% Non-fibrous (Other)	None Detected	
412313753-0062A	Bathroom Floor, 2 Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Non-Fibrous Homogeneous				
78-Tan Flooring	Build 3 - K & L	Tan	5% Synthetic	20% Ca Carbonate	None Detected	
412313753-0062B	Bathroom Floor, 2 Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Non-Fibrous Homogeneous		75% Non-fibrous (Other)		



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Non-Asbestos			<u>Asbestos</u>
		Appearance	% Fibrous	% Non-Fibrous	% Type
78-Mastic/Leveler 412313753-0062C	Build 3 - K & L Bathroom Floor, 2 Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Gray/Yellow Non-Fibrous Heterogeneous	2% Cellulose	5% Ca Carbonate 93% Non-fibrous (Other)	None Detected
80-Flooring 412313753-0063	Build 3 - I & J Kit Floor - Marble Pat Floor & Mastic	Tan Fibrous Heterogeneous	10% Synthetic 10% Glass	20% Ca Carbonate 60% Non-fibrous (Other)	None Detected
80-Mastic	Build 3 - I & J Kit Floor - Marble Pat Floor & Mastic	Yellow Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
	Build 3 - I & J Kit		5% Synthetic	20% Ca Carbonate	None Detected
81-Flooring 412313753-0064	Floor - Marble Pat Floor & Mastic	Gray/Beige Non-Fibrous Homogeneous	5% Synthetic	75% Non-fibrous (Other)	None Detected
81-Mastic/Leveler	Build 3 - I & J Kit Floor - Marble Pat Floor & Mastic	Gray/Yellow Non-Fibrous Heterogeneous	2% Cellulose	10% Ca Carbonate 88% Non-fibrous (Other)	None Detected
83-Tape 412313753-0065	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	White Fibrous Homogeneous	40% Synthetic 55% Glass	5% Non-fibrous (Other)	None Detected
83-Joint Compound	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 3% Perlite 17% Non-fibrous (Other)	None Detected
83-Drywall	Build 3 - I, J, K, L Walls & Ceiling -	Beige Non-Fibrous	3% Cellulose <1% Glass	97% Non-fibrous (Other)	None Detected
412313753-0065B	Drywall & JC	Homogeneous			
84-Tape 412313753-0066	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	White Fibrous Homogeneous	40% Synthetic 55% Glass	5% Non-fibrous (Other)	None Detected
84-Joint Compound 412313753-0066A	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 3% Perlite 17% Non-fibrous (Other)	None Detected
84-Drywall	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	Beige Non-Fibrous Homogeneous	3% Cellulose <1% Glass	97% Non-fibrous (Other)	None Detected
412313753-0066B 85-Tape 412313753-0067	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	White Fibrous Homogeneous	40% Synthetic 55% Glass	5% Non-fibrous (Other)	None Detected
85-Joint Compound	Build 3 - I, J, K, L Walls & Ceiling -	White Non-Fibrous		80% Ca Carbonate 3% Perlite	None Detected
85-Drywall	Drywall & JC Build 3 - I, J, K, L Walls & Ceiling -	Homogeneous Beige Non-Fibrous	3% Cellulose <1% Glass	17% Non-fibrous (Other) 97% Non-fibrous (Other)	None Detected
412313753-0067B	Drywall & JC	Homogeneous	EE0/ C-11:-1	50/ Non 5h (Oth)	None Detected
86-Tape 412313753-0068	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	White Fibrous Homogeneous	55% Cellulose 40% Synthetic	5% Non-fibrous (Other)	None Detected
86-Joint Compound	Build 3 - I, J, K, L Walls & Ceiling -	White Non-Fibrous		80% Ca Carbonate 4% Perlite	None Detected
412313753-0068A	Drywall & JC	Homogeneous		16% Non-fibrous (Other)	
86-Drywall 412313753-0068B	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	Beige Non-Fibrous Homogeneous	3% Cellulose 2% Glass	95% Non-fibrous (Other)	None Detected
87-Tape	Build 3 - I, J, K, L Walls & Ceiling -	White Fibrous	40% Cellulose 60% Synthetic		None Detected
412313753-0069	Drywall & JC	Homogeneous	3370 Synthetic		



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

			Non-Asbes	<u>stos</u>	<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
87-Joint Compound 412313753-0069A	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
87-Drywall	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	White Non-Fibrous	10% Cellulose <1% Glass	90% Non-fibrous (Other)	None Detected
<u>412313753-0069B</u> 88-Tape	Build 3 - I, J, K, L Walls & Ceiling -	Homogeneous White Fibrous	40% Cellulose 60% Synthetic		None Detected
412313753-0070	Drywall & JC	Homogeneous			
88-Joint Compound	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
412313753-0070A	•	Homogeneous	400/ O. H. L	000/ Nov. Electric (Others)	None Batasta I
88-Drywall 412313753-0070B	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous	10% Cellulose <1% Glass	90% Non-fibrous (Other)	None Detected
89-Tape	Build 3 - I, J, K, L Walls & Ceiling -	White Fibrous	40% Cellulose 60% Synthetic		None Detected
412313753-0071	Drywall & JC	Homogeneous			
89-Joint Compound 412313753-0071A	Build 3 - I, J, K, L Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
	Build 3 - I, J, K, L	White	5% Cellulose	95% Non-fibrous (Other)	None Detected
89-Drywall 412313753-0071B	Walls & Ceiling - Drywall & JC	Non-Fibrous Homogeneous	<1% Glass	55 /0 NOTHINIOUS (OTHER)	None Detected
90-Tan Coat	Build 3 - Entry Stair Walls & Upstairs	Tan Non-Fibrous		60% Quartz 15% Ca Carbonate	None Detected
412313753-0072	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous		25% Non-fibrous (Other)	
90-Gray Coat	Build 3 - Entry Stair	Gray	2% Cellulose	60% Quartz	None Detected
412313753-0072A	Walls & Upstairs Ceiling - Text Plaster & Drywall w/ No JC	Non-Fibrous Homogeneous	<1% Glass	38% Non-fibrous (Other)	
90-Drywall	Build 3 - Entry Stair	Gray	12% Cellulose	88% Non-fibrous (Other)	None Detected
412313753-0072B	Walls & Upstairs Ceiling - Text Plaster & Drywall w/ No JC	Non-Fibrous Homogeneous			
91-Tan Coat	Build 3 - Entry Stair	White		60% Quartz	None Detected
412313753-0073	Walls & Upstairs Ceiling - Text Plaster & Drywall w/ No JC	Non-Fibrous Homogeneous		10% Ca Carbonate 30% Non-fibrous (Other)	_
No drywall present.	a Drywaii w/ NO JC				
91-Gray Coat	Build 3 - Entry Stair	Gray	2% Cellulose	60% Quartz	None Detected
412313753-0073A	Walls & Upstairs Ceiling - Text Plaster & Drywall w/ No JC	Non-Fibrous Homogeneous		38% Non-fibrous (Other)	= -
92-Tan Coat	Build 3 - Entry Stair Walls & Upstairs	Tan Non-Fibrous		60% Quartz 10% Ca Carbonate	None Detected
412313753-0074	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous		30% Non-fibrous (Other)	
92-Gray Coat	Build 3 - Entry Stair Walls & Upstairs	Gray Non-Fibrous		60% Quartz 40% Non-fibrous (Other)	None Detected
412313753-0074A	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous		V- /	
92-Drywall	Build 3 - Entry Stair Walls & Upstairs	Gray Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
412313753-0074B	Ceiling - Text Plaster	Homogeneous			



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

_			Non-Asbes		Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
93-Tan Coat 12313753-0075	Build 3 - Entry Stair Walls & Upstairs Ceiling - Text Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		60% Quartz 10% Ca Carbonate 30% Non-fibrous (Other)	None Detected
93-Gray Coat	Build 3 - Entry Stair Walls & Upstairs	Gray Non-Fibrous		60% Quartz 40% Non-fibrous (Other)	None Detected
12313753-0075A	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous			
93-Drywall	Build 3 - Entry Stair Walls & Upstairs	Gray Non-Fibrous	8% Cellulose	92% Non-fibrous (Other)	None Detected
12313753-0075B	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous			
4-Tan Coat	Build 3 - Entry Stair Walls & Upstairs	Tan/White Non-Fibrous		20% Quartz 5% Ca Carbonate	None Detected
12313753-0076	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous		75% Non-fibrous (Other)	
94-Gray Coat	Build 3 - Entry Stair Walls & Upstairs	Gray Non-Fibrous		40% Quartz 60% Non-fibrous (Other)	None Detected
12313753-0076A	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous		· ·	
4-Drywall	Build 3 - Entry Stair Walls & Upstairs	Gray Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
12313753-0076B	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous			
5-Tan Coat	Build 3 - Entry Stair Walls & Upstairs	Tan/White Non-Fibrous		25% Quartz 5% Ca Carbonate	None Detected
12313753-0077	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous		70% Non-fibrous (Other)	
lo drywall present.	·				
95-Gray Coat	Build 3 - Entry Stair Walls & Upstairs	Gray Non-Fibrous		40% Quartz 60% Non-fibrous (Other)	None Detected
12313753-0077A	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous		oo w Horringrous (Outlet)	
5-Tape	Build 3 - Entry Stair Walls & Upstairs	Beige Fibrous	99% Cellulose	1% Non-fibrous (Other)	None Detected
12313753-0077B	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous			
5-Joint Compound	Build 3 - Entry Stair Walls & Upstairs	White Non-Fibrous		60% Ca Carbonate 40% Non-fibrous (Other)	None Detected
12313753-0077C	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous		.s.a. non norses (other)	
6-Tan Coat	Build 3 - Entry Stair Walls & Upstairs	Tan/White Non-Fibrous		25% Quartz 5% Ca Carbonate	None Detected
12313753-0078	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous		70% Non-fibrous (Other)	
6-Gray Coat	Build 3 - Entry Stair Walls & Upstairs	Gray Non-Fibrous	<1% Cellulose	40% Quartz 60% Non-fibrous (Other)	None Detected
12313753-0078A	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous			
6-Drywall	Build 3 - Entry Stair Walls & Upstairs	Gray Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
12313753-0078B	Ceiling - Text Plaster & Drywall w/ No JC	Homogeneous			
7-Shingle	Build 4 - Roof - 1 Shingle, 1 Felt	Brown/Gray/Black Fibrous	15% Glass	5% Quartz 15% Ca Carbonate	None Detected
12313753-0079		Heterogeneous		65% Non-fibrous (Other)	
97-Felt	Build 4 - Roof - 1 Shingle, 1 Felt	Brown/Black Fibrous	80% Cellulose <1% Glass	20% Non-fibrous (Other)	None Detected
112313753-0079A	•	Homogeneous			



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample			<u>Asbestos</u>		
	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
97-Insulation	Build 4 - Roof - 1 Shingle, 1 Felt	White Fibrous Homogeneous	99% Glass	1% Non-fibrous (Other)	None Detected
98-Shingle	Build 4 - Roof - 1 Shingle, 1 Felt	Gray/Black Fibrous	10% Glass	2% Quartz 20% Ca Carbonate	None Detected
412313753-0080 98-Felt	Build 4 - Roof - 1 Shingle, 1 Felt	Homogeneous Black Fibrous	90% Cellulose	68% Non-fibrous (Other) 10% Non-fibrous (Other)	None Detected
412313753-0080A 98-Insulation	Build 4 - Roof - 1	Homogeneous White	99% Glass	1% Non-fibrous (Other)	None Detected
112313753-0080B	Shingle, 1 Felt	Fibrous Homogeneous		,	
100	Build 4 - Exterior - Door & Window Caulk	White Non-Fibrous		100% Non-fibrous (Other)	None Detected
112313753-0081		Homogeneous			
101 412313753-0082	Build 4 - Exterior - Door & Window Caulk	White Non-Fibrous		2% Ca Carbonate 98% Non-fibrous (Other)	None Detected
103	Build 4 - ABCD Entry Stairs - Stair Tread	Homogeneous Brown/Tan Non-Fibrous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
112313753-0083 104	Mastic Build 4 - ABCD Entry	Homogeneous Gray/Beige	<1% Cellulose	100% Non-fibrous (Other)	None Detected
112313753-0084	Stairs - Stair Tread Mastic	Non-Fibrous Homogeneous			
06-Paneling	Build 4 - ABCD Bathrm - Tub	Tan/White/Yellow Non-Fibrous		<1% Ca Carbonate 100% Non-fibrous (Other)	None Detected
412313753-0085	Surround Mastic	Homogeneous		450/ Co Contracts	Nama Data ata d
106-Mastic 112313753-0085A	Build 4 - ABCD Bathrm - Tub Surround Mastic	Tan Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
107-Paneling	Build 4 - ABCD Bathrm - Tub	White/Beige Non-Fibrous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
412313753-0086	Surround Mastic	Homogeneous		. ,	
107-Mastic	Build 4 - ABCD Bathrm - Tub	Tan Non-Fibrous		100% Non-fibrous (Other)	None Detected
112313753-0086A	Surround Mastic	Homogeneous			
108-Paneling 112313753-0086B	Build 4 - ABCD Bathrm - Tub Surround Mastic	White/Beige Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
109-Vinyl	Build 4 - ABCD Kit & Bath - Marble Pat.	Beige Fibrous	6% Synthetic 10% Glass	25% Ca Carbonate 59% Non-fibrous (Other)	None Detected
412313753-0087	Vinyl w/ Mastic	Heterogeneous			
109-Mastic	Build 4 - ABCD Kit & Bath - Marble Pat. Vinyl w/ Mastic	Yellow Non-Fibrous	<1% Cellulose	<1% Ca Carbonate 100% Non-fibrous (Other)	None Detected
	Vinyl w/ Mastic	Homogeneous Cray/White/Reige	20/ Cumthatia	20% Co Corbonata	None Detected
110-Vinyl 112313753-0088	Build 4 - ABCD Kit & Bath - Marble Pat. Vinyl w/ Mastic	Gray/White/Beige Fibrous Homogeneous	2% Synthetic 5% Glass	20% Ca Carbonate 73% Non-fibrous (Other)	None Detected
110-Mastic	Build 4 - ABCD Kit & Bath - Marble Pat.	Yellow Non-Fibrous	2% Cellulose	98% Non-fibrous (Other)	None Detected
112313753-0088A	Vinyl w/ Mastic	Homogeneous			
112-Tape	Build 4 - ABCD Walls & Ceiling - Drywall &	White Fibrous	40% Synthetic 55% Glass	5% Non-fibrous (Other)	None Detected
412313753-0089	JC	Homogeneous			
112-Joint Compound	Build 4 - ABCD Walls & Ceiling - Drywall &	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
412313753-0089A	JC	Homogeneous			



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

		Non-Asbestos			<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
112-Drywall	Build 4 - ABCD Walls & Ceiling - Drywall & JC	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
113-Tape	Build 4 - ABCD Walls & Ceiling - Drywall & JC	White Fibrous Homogeneous	40% Synthetic 55% Glass	5% Non-fibrous (Other)	None Detected
113-Joint Compound	Build 4 - ABCD Walls & Ceiling - Drywall &	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
113-Drywall	JC Build 4 - ABCD Walls & Ceiling - Drywall &	Homogeneous Gray Non-Fibrous	5% Cellulose	95% Non-fibrous (Other)	None Detected
412313753-0090B	JC	Homogeneous			
114-Tape 412313753-0091	Build 4 - ABCD Walls & Ceiling - Drywall & JC	White Fibrous Homogeneous	40% Synthetic 55% Glass	5% Non-fibrous (Other)	None Detected
	Build 4 - ABCD Walls	White		80% Ca Carbonate	None Detected
114-Joint Compound 412313753-0091A	& Ceiling - Drywall & JC	Non-Fibrous Homogeneous		20% Non-fibrous (Other)	None Detected
114-Drywall	Build 4 - ABCD Walls & Ceiling - Drywall &	Gray Non-Fibrous	4% Cellulose	96% Non-fibrous (Other)	None Detected
412313753-0091B	JC	Homogeneous			
115-Tape	Build 4 - ABCD Walls & Ceiling - Drywall &	White Fibrous	40% Synthetic 55% Glass	5% Non-fibrous (Other)	None Detected
412313753-0092	JC	Homogeneous			
115-Joint Compound 412313753-0092A	Build 4 - ABCD Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
115-Drywall	Build 4 - ABCD Walls	Gray	3% Cellulose	97% Non-fibrous (Other)	None Detected
412313753-0092B	& Ceiling - Drywall & JC	Non-Fibrous Homogeneous	070 Gendiose	or when librous (Other)	None Beleated
116-Tape	Build 4 - ABCD Walls & Ceiling - Drywall &	White Fibrous	10% Synthetic 90% Glass		None Detected
412313753-0093	JC	Homogeneous			
116-Joint Compound	Build 4 - ABCD Walls & Ceiling - Drywall &	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
412313753-0093A	JC	Homogeneous			
116-Drywall 412313753-0093B	Build 4 - ABCD Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
117-Tape	Build 4 - ABCD Walls & Ceiling - Drywall &	White Fibrous	10% Synthetic 90% Glass		None Detected
412313753-0094	JC	Homogeneous			
117-Joint Compound	Build 4 - ABCD Walls & Ceiling - Drywall &	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
412313753-0094A	JC	Homogeneous			
117-Drywall 412313753-0094B	Build 4 - ABCD Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
		White	10% Synthatia		None Detected
118-Tape 412313753-0095	Build 4 - ABCD Walls & Ceiling - Drywall & JC	vvnite Fibrous Homogeneous	10% Synthetic 90% Glass		None Detected
118-Joint Compound	Build 4 - ABCD Walls	White		80% Ca Carbonate	None Detected
412313753-0095A	& Ceiling - Drywall & JC	Non-Fibrous Homogeneous		20% Non-fibrous (Other)	
118-Drywall	Build 4 - ABCD Walls & Ceiling - Drywall &	White Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
412313753-0095B	JC	Homogeneous			



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

		Non-Asbestos			<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
119-Texture 412313753-0096	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
119-Tan Coat 412313753-0096A	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Tan/White Non-Fibrous Homogeneous		55% Quartz 10% Ca Carbonate 35% Non-fibrous (Other)	None Detected
119-Gray Coat 412313753-0096B	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	2% Cellulose	60% Quartz 38% Non-fibrous (Other)	None Detected
119-Drywall 412313753-0096C	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
120-Texture 412313753-0097	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
120-Tan Coat 412313753-0097A	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Tan/White Non-Fibrous Homogeneous		55% Quartz 10% Ca Carbonate 35% Non-fibrous (Other)	None Detected
120-Gray Coat 412313753-0097B	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		60% Quartz 40% Non-fibrous (Other)	None Detected
120-Drywall 412313753-0097C	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
121-Texture 412313753-0098	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		10% Ca Carbonate 90% Non-fibrous (Other)	None Detected
121-Tan Coat 412313753-0098A	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		60% Quartz 10% Ca Carbonate 30% Non-fibrous (Other)	None Detected
121-Gray Coat 412313753-0098B	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	2% Cellulose	60% Quartz 38% Non-fibrous (Other)	None Detected
121-Drywall 412313753-0098C	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	12% Cellulose	88% Non-fibrous (Other)	None Detected
122-Texture 412313753-0099	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		10% Ca Carbonate 90% Non-fibrous (Other)	None Detected
122-Tan Coat 412313753-0099A	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Tan Non-Fibrous Homogeneous		60% Quartz 10% Ca Carbonate 30% Non-fibrous (Other)	None Detected



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample			Non-Asbe	<u>stos</u>	<u>Asbestos</u>
	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
122-Gray Coat 412313753-0099B	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	2% Cellulose	60% Quartz 38% Non-fibrous (Other)	None Detected
122-Drywall 412313753-0099C	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
123-Texture 412313753-0100	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		10% Ca Carbonate 90% Non-fibrous (Other)	None Detected
123-Tan Coat 412313753-0100A	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Tan/White Non-Fibrous Homogeneous		20% Quartz 5% Ca Carbonate 75% Non-fibrous (Other)	None Detected
123-Gray Coat 412313753-0100B	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	<1% Cellulose	40% Quartz 60% Non-fibrous (Other)	None Detected
123-Drywall 412313753-0100C	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	10% Cellulose <1% Glass	90% Non-fibrous (Other)	None Detected
124-Texture 412313753-0101	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		10% Ca Carbonate 90% Non-fibrous (Other)	None Detected
124-Tan Coat 412313753-0101A	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Tan/White Non-Fibrous Homogeneous		25% Quartz 5% Ca Carbonate 70% Non-fibrous (Other)	None Detected
124-Gray Coat 412313753-0101B	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		40% Quartz 60% Non-fibrous (Other)	None Detected
124-Drywall 412313753-0101C	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
125-Texture 412313753-0102	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		10% Ca Carbonate 90% Non-fibrous (Other)	None Detected
No drywall present.					
125-Tan Coat 412313753-0102A	Build 4 - C & D Ceilings Upstairs - Text Plaster & Drywall	Tan/White Non-Fibrous Homogeneous		20% Quartz 5% Ca Carbonate 75% Non-fibrous (Other)	None Detected
125-Gray Coat	w/ No JC Build 4 - C & D Ceilings Upstairs -	Gray Non-Fibrous		40% Quartz 60% Non-fibrous (Other)	None Detected
412313753-0102B	Text Plaster & Drywall w/ No JC	Homogeneous		oo a non abload (odilor)	
126-Shingle 412313753-0103	Build 5 - Roof - 1 Shingle, 3 Felt	Gray/Black Fibrous Homogeneous	15% Glass	10% Quartz 20% Ca Carbonate 55% Non-fibrous (Other)	None Detected
126-Felt 1	Build 5 - Roof - 1 Shingle, 3 Felt	Black Fibrous	90% Cellulose	10% Non-fibrous (Other)	None Detected
412313753-0103A	-	Homogeneous			



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	_	Non-Asbes	<u>Asbestos</u>	
		Appearance	% Fibrous	% Non-Fibrous	% Type
126-Felt 2	Build 5 - Roof - 1 Shingle, 3 Felt	Black Fibrous	90% Cellulose	10% Non-fibrous (Other)	None Detected
112313753-0103B		Homogeneous			
126-Felt 3	Build 5 - Roof - 1 Shingle, 3 Felt	Black Fibrous	90% Cellulose	10% Non-fibrous (Other)	None Detected
112313753-0103C		Homogeneous			
127-Shingle	Build 5 - Roof - 1 Shingle, 3 Felt	Gray/Black Fibrous	10% Glass	2% Quartz 20% Ca Carbonate	None Detected
112313753-0104		Homogeneous		68% Non-fibrous (Other)	
27-Felt 1	Build 5 - Roof - 1 Shingle, 3 Felt	Black Fibrous	90% Cellulose	10% Non-fibrous (Other)	None Detected
112313753-0104A		Homogeneous			
127-Felt 2	Build 5 - Roof - 1 Shingle, 3 Felt	Black Fibrous	80% Cellulose	10% Mica 10% Non-fibrous (Other)	None Detected
112313753-0104B		Homogeneous			
127-Felt 3	Build 5 - Roof - 1 Shingle, 3 Felt	Black Fibrous	90% Cellulose	10% Non-fibrous (Other)	None Detected
412313753-0104C		Homogeneous			
129	Build 5 - Exterior - Door & Window Caulk	White Non-Fibrous		<1% Ca Carbonate 100% Non-fibrous (Other)	None Detected
112313753-0105		Homogeneous			
130	Build 5 - Exterior - Door & Window Caulk	White Non-Fibrous		2% Ca Carbonate 98% Non-fibrous (Other)	None Detected
112313753-0106		Homogeneous			
132	Build 5 - Entryway Stairs - Stair Tread	Beige Non-Fibrous	<1% Cellulose	15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
412313753-0107	Mastic	Homogeneous			
133	Build 5 - Entryway Stairs - Stair Tread	Beige Non-Fibrous		100% Non-fibrous (Other)	None Detected
112313753-0108	Mastic	Homogeneous			
135	Build 5 - EFGH Bathrm - Tub	Yellow Non-Fibrous	<1% Cellulose	<1% Ca Carbonate 100% Non-fibrous (Other)	None Detected
112313753-0109	Surround Mastic Only	Homogeneous			
136	Build 5 - EFGH Bathrm - Tub	Tan Non-Fibrous		100% Non-fibrous (Other)	None Detected
112313753-0110	Surround Mastic Only	Homogeneous			
138-Flooring 412313753-0111	Build 5 - EFGH Kitchen & Bath - Marble Text Floor & Mastic	Beige Non-Fibrous Homogeneous	5% Glass	25% Ca Carbonate 70% Non-fibrous (Other)	None Detected
138-Mastic	Build 5 - EFGH Kitchen & Bath -	Yellow Non-Fibrous	<1% Cellulose	100% Non-fibrous (Other)	None Detected
412313753-0111A	Marble Text Floor & Mastic	Homogeneous			
139-Flooring	Build 5 - EFGH Kitchen & Bath -	Gray/Tan Fibrous	5% Glass	20% Ca Carbonate 75% Non-fibrous (Other)	None Detected
112313753-0112	Marble Text Floor & Mastic	Homogeneous			
139-Mastic	Build 5 - EFGH Kitchen & Bath -	Yellow Non-Fibrous	2% Cellulose	98% Non-fibrous (Other)	None Detected
112313753-0112A	Marble Text Floor & Mastic	Homogeneous			
141-Tape	Build 5 - EFGH Ceiling & Walls -	White Fibrous	50% Synthetic 50% Glass		None Detected
112313753-0113	Drywall & JC	Homogeneous			
141-Joint Compound	Build 5 - EFGH Ceiling & Walls -	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
412313753-0113A	Drywall & JC	Homogeneous		\ - /	



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample		Non-Asbestos			<u>Asbestos</u>
	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
141-Drywall	Build 5 - EFGH Ceiling & Walls -	Gray Non-Fibrous	5% Cellulose	95% Non-fibrous (Other)	None Detected
412313753-0113B	Drywall & JC	Homogeneous	500/ 0		
142-Tape 412313753-0114	Build 5 - EFGH Ceiling & Walls - Drywall & JC	White Fibrous Homogeneous	50% Synthetic 50% Glass		None Detected
				00% 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Non-Batastad
142-Joint Compound	Build 5 - EFGH Ceiling & Walls - Drywall & JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
	Build 5 - EFGH		50/ O . II . I	05% Nov. 51 (011)	N D. t t I
142-Drywall #12313753-0114B	Ceiling & Walls - Drywall & JC	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
			COO/ Compth - #:-		Nama Datastad
143-Tape	Build 5 - EFGH Ceiling & Walls -	White Fibrous	50% Synthetic 50% Glass		None Detected
4 12313753-0115	Drywall & JC	Homogeneous	00 /0 Old03		
143-Joint Compound	Build 5 - EFGH	White		80% Ca Carbonate	None Detected
412313753-0115A	Ceiling & Walls - Drywall & JC	Non-Fibrous Homogeneous		20% Non-fibrous (Other)	20.00.00
143-Drywall	Build 5 - EFGH	Gray	5% Cellulose	95% Non-fibrous (Other)	None Detected
· , · · -···	Ceiling & Walls -	Non-Fibrous		ζ- /	·
412313753-0115B	Drywall & JC	Homogeneous			
144-Tape	Build 5 - EFGH Ceiling & Walls -	White Fibrous	50% Synthetic 50% Glass		None Detected
112313753-0116	Drywall & JC	Homogeneous			
144-Joint Compound	Build 5 - EFGH Ceiling & Walls -	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
412313753-0116A	Drywall & JC	Homogeneous			
144-Drywall	Build 5 - EFGH Ceiling & Walls -	Gray Non-Fibrous	5% Cellulose	95% Non-fibrous (Other)	None Detected
412313753-0116B	Drywall & JC	Homogeneous			
145-Tape	Build 5 - EFGH	White	20% Synthetic		None Detected
412313753-0117	Ceiling & Walls - Drywall & JC	Fibrous Homogeneous	80% Glass		
145-Joint Compound	Build 5 - EFGH	White		80% Ca Carbonate	None Detected
143-30iiii Compound	Ceiling & Walls -	Non-Fibrous		20% Non-fibrous (Other)	None Detected
412313753-0117A	Drywall & JC	Homogeneous		,	
145-Drywall	Build 5 - EFGH	Gray	10% Cellulose	90% Non-fibrous (Other)	None Detected
,	Ceiling & Walls -	Non-Fibrous		, ,	
412313753-0117B	Drywall & JC	Homogeneous			
146-Tape	Build 5 - EFGH Ceiling & Walls -	White Fibrous	20% Synthetic 80% Glass		None Detected
412313753-0118	Drywall & JC	Homogeneous			
146-Joint Compound	Build 5 - EFGH	White		80% Ca Carbonate	None Detected
412313753-0118A	Ceiling & Walls - Drywall & JC	Non-Fibrous Homogeneous		20% Non-fibrous (Other)	
	Build 5 - EFGH		10% Cellulose	90% Non fibrage (Other)	None Detected
146-Drywall 412313753-0118B	Ceiling & Walls - Drywall & JC	Gray Non-Fibrous Homogeneous	1070 Cellulose	90% Non-fibrous (Other)	None Detected
147-Tape	Build 5 - EFGH	White	20% Synthetic		None Detected
•	Ceiling & Walls -	Fibrous	80% Glass		Mone Defected
412313753-0119	Drywall & JC	Homogeneous		000/ 0 - 0 - 1	Non-British
147-Joint Compound	Build 5 - EFGH Ceiling & Walls -	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
412313753-0119A	Drywall & JC	Homogeneous			
147-Drywall	Build 5 - EFGH Ceiling & Walls -	Gray Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
412313753-0119B	Drywall & JC	Homogeneous			



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample		Non-Asbestos			<u>Asbestos</u>
	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
148-White Coat	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		50% Quartz 50% Non-fibrous (Other)	None Detected
148-Gray Coat 412313753-0120A	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	<1% Cellulose	60% Quartz 40% Non-fibrous (Other)	None Detected
148-Drywall 412313753-0120B	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
149-Texture 412313753-0121	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
149-White Coat 412313753-0121A	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		50% Quartz 50% Non-fibrous (Other)	None Detected
149-Gray Coat 412313753-0121B	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	<1% Cellulose	60% Quartz 40% Non-fibrous (Other)	None Detected
149-Drywall 412313753-0121C	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
150-White Coat 412313753-0122	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		50% Quartz 50% Non-fibrous (Other)	None Detected
150-Gray Coat 412313753-0122A	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	<1% Cellulose	60% Quartz 40% Non-fibrous (Other)	None Detected
150-Drywall 412313753-0122B	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
151-Texture 412313753-0123	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		30% Ca Carbonate 70% Non-fibrous (Other)	None Detected
151-White Coat 412313753-0123A	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		50% Quartz 50% Non-fibrous (Other)	None Detected
151-Gray Coat 412313753-0123B	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	<1% Cellulose	60% Quartz 40% Non-fibrous (Other)	None Detected
151-Drywall 412313753-0123C	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Non-Asbestos			<u>Asbestos</u>
		Appearance	% Fibrous	% Non-Fibrous	% Type
152-Texture 412313753-0124	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
152-White Coat 412313753-0124A	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		20% Quartz 15% Ca Carbonate 65% Non-fibrous (Other)	None Detected
152-Gray Coat	Build 5 - G & H Entry Stairs & Ceiling - Text	Gray Non-Fibrous		30% Quartz 70% Non-fibrous (Other)	None Detected
412313753-0124B	Plaster & Drywall w/ No JC	Homogeneous			
152-Drywall 412313753-0124C	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/	White Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
153-Texture 412313753-0125	No JC Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/	White Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
153-White Coat	No JC Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		20% Quartz 10% Ca Carbonate 70% Non-fibrous (Other)	None Detected
153-Gray Coat 412313753-0125B	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	<1% Cellulose	30% Quartz 70% Non-fibrous (Other)	None Detected
153-Drywall 412313753-0125C	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
154-Texture 412313753-0126	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
154-White Coat	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		20% Quartz 10% Ca Carbonate 70% Non-fibrous (Other)	None Detected
154-Gray Coat 112313753-0126B	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		30% Quartz 70% Non-fibrous (Other)	None Detected
154-Drywall 112313753-0126C	Build 5 - G & H Entry Stairs & Ceiling - Text Plaster & Drywall w/	White Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
155-Shingle	No JC Build 6 - Roof - 1 Shingle, 2 Felt	Gray/Black Fibrous	15% Glass	5% Quartz 10% Ca Carbonate	None Detected
412313753-0127		Homogeneous		70% Non-fibrous (Other)	
155-Felt 1	Build 6 - Roof - 1 Shingle, 2 Felt	Black Fibrous	90% Cellulose	10% Non-fibrous (Other)	None Detected
412313753-0127A 155-Felt 2	Build 6 - Roof - 1	Homogeneous Black	90% Cellulose	10% Non-fibrous (Other)	None Detected
412313753-0127B	Shingle, 2 Felt	Fibrous Homogeneous			



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample		Non-Asbestos			<u>Asbestos</u>
	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
156-Shingle 412313753-0128	Build 6 - Roof - 1 Shingle, 2 Felt	Gray/Black Fibrous Homogeneous	15% Glass	2% Quartz 20% Ca Carbonate 63% Non-fibrous (Other)	None Detected
156-Felt 1	Build 6 - Roof - 1 Shingle, 2 Felt	Black Fibrous	80% Cellulose	20% Non-fibrous (Other)	None Detected
412313753-0128A	Shirigle, 2 i eli	Homogeneous			
156-Felt 2	Build 6 - Roof - 1 Shingle, 2 Felt	Black Fibrous	80% Cellulose	20% Non-fibrous (Other)	None Detected
412313753-0128B		Homogeneous			
158	Build 6 - Exterior - Door & Window Caulk	Gray/Clear Non-Fibrous		<1% Quartz 100% Non-fibrous (Other)	None Detected
412313753-0129		Homogeneous			
159	Build 6 - Exterior - Door & Window Caulk	Gray/Clear Non-Fibrous		2% Ca Carbonate 98% Non-fibrous (Other)	None Detected
412313753-0130		Homogeneous			
161	Build 6 - Entry Stairs - Stair Tread Mastic	Beige Non-Fibrous	<1% Cellulose	10% Ca Carbonate 90% Non-fibrous (Other)	None Detected
412313753-0131	Dallo E : O: :	Homogeneous	.40/ 0 " '	4000/ Nov. 51 (21)	Maria Data data
162 412313753-0132	Build 6 - Entry Stairs - Stair Tread Mastic	Beige Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (Other)	None Detected
	Build 6 - ABCD	Tan/White		20% Ca Carbonate	None Detected
164-Flooring 412313753-0133	Kitchens - Marble Text Pat Flr w/ Mastic	Non-Fibrous Homogeneous		80% Non-fibrous (Other)	Notic Defected
164-Mastic	Build 6 - ABCD	Tan/Yellow	<1% Cellulose	100% Non-fibrous (Other)	None Detected
412313753-0133A	Kitchens - Marble Text Pat Flr w/ Mastic	Non-Fibrous Homogeneous			
165-Flooring	Build 6 - ABCD	Brown/Tan/White	5% Glass	25% Ca Carbonate	None Detected
412313753-0134	Kitchens - Marble Text Pat Flr w/ Mastic	Fibrous Homogeneous		70% Non-fibrous (Other)	
165-Mastic	Build 6 - ABCD	Tan	2% Cellulose	98% Non-fibrous (Other)	None Detected
412313753-0134A	Kitchens - Marble Text Pat FIr w/ Mastic	Non-Fibrous Homogeneous			
167-Tape	Build 6 - ABCD Walls & Ceiling - Drywall &	Yellow Fibrous	99% Glass	1% Non-fibrous (Other)	None Detected
412313753-0135	JC ,	Homogeneous			
167-Joint Compound	Build 6 - ABCD Walls & Ceiling - Drywall &	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
412313753-0135A	JC	Homogeneous			
167-Drywall	Build 6 - ABCD Walls & Ceiling - Drywall &	Gray Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
412313753-0135B	JC	Homogeneous	200/ 0/	40/ 14 50 (20)	N 5
168-Tape	Build 6 - ABCD Walls & Ceiling - Drywall &	Yellow Fibrous	99% Glass	1% Non-fibrous (Other)	None Detected
412313753-0136	JC	Homogeneous		200/ 0- 0-1	Nama District
168-Joint Compound	Build 6 - ABCD Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
168-Drywall	Build 6 - ABCD Walls	Gray	10% Cellulose	90% Non-fibrous (Other)	None Detected
412313753-0136B	& Ceiling - Drywall & JC	Non-Fibrous Homogeneous			
169-Tape	Build 6 - ABCD Walls & Ceiling - Drywall &	Yellow Fibrous	99% Glass	1% Non-fibrous (Other)	None Detected
412313753-0137	JC	Homogeneous			
169-Joint Compound	Build 6 - ABCD Walls & Ceiling - Drywall &	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
412313753-0137A	JC	Homogeneous		,	



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

		Non-Asbestos			<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
169-Drywall	Build 6 - ABCD Walls & Ceiling - Drywall & JC	Gray Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
170-Tape	Build 6 - ABCD Walls & Ceiling - Drywall &	Yellow Fibrous	99% Glass	1% Non-fibrous (Other)	None Detected
412313753-0138	JC	Homogeneous			
170-Joint Compound	Build 6 - ABCD Walls & Ceiling - Drywall & JC	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
412313753-0138A		Homogeneous	400/ 0 . II	000/ Non Elmon (Other)	N D. t t I
170-Drywall 412313753-0138B	Build 6 - ABCD Walls & Ceiling - Drywall & JC	Gray Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
171-Tape	Build 6 - ABCD Walls & Ceiling - Drywall &	Yellow Fibrous	99% Glass	1% Non-fibrous (Other)	None Detected
412313753-0139	JC	Homogeneous			
171-Joint Compound	Build 6 - ABCD Walls & Ceiling - Drywall & JC	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
412313753-0139A		Homogeneous	400/ 0 .	000/ Non Standard (Other)	N D. t t I
171-Drywall 412313753-0139B	Build 6 - ABCD Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
 172-Tape	Build 6 - ABCD Walls	Yellow	99% Glass	1% Non-fibrous (Other)	None Detected
412313753-0140	& Ceiling - Drywall & JC	Fibrous Homogeneous	33 % Glass	170 Norrhbrods (Other)	None Beledied
172-Joint Compound	Build 6 - ABCD Walls	White		80% Ca Carbonate	None Detected
·	& Ceiling - Drywall &	Non-Fibrous		20% Non-fibrous (Other)	
412313753-0140A	JC	Homogeneous			
172-Drywall 412313753-0140B	Build 6 - ABCD Walls & Ceiling - Drywall & JC	White Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
	Build 6 - ABCD Walls	-	99% Glass	19/ Non fibrage (Other)	None Detected
173-Tape 412313753-0141	& Ceiling - Drywall & JC	Yellow Fibrous Homogeneous	99% Glass	1% Non-fibrous (Other)	None Detected
173-Joint Compound	Build 6 - ABCD Walls	White		80% Ca Carbonate	None Detected
412313753-0141A	& Ceiling - Drywall & JC	Non-Fibrous Homogeneous		20% Non-fibrous (Other)	
173-Drywall	Build 6 - ABCD Walls & Ceiling - Drywall &	White Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
412313753-0141B	JC	Homogeneous			
174-Texture	Build 6 - C & D Ceilings & Entry	White Non-Fibrous		75% Ca Carbonate 5% Perlite	None Detected
412313753-0142	Stairs Walls - Text. Plaster & Drywall w/ No JC	Homogeneous		20% Non-fibrous (Other)	
174-White Coat	Build 6 - C & D	White		40% Quartz	None Detected
412313753-0142A	Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	Non-Fibrous Homogeneous		15% Ca Carbonate 45% Non-fibrous (Other)	
174-Gray Coat	Build 6 - C & D	Gray	<1% Cellulose	60% Quartz	None Detected
412313753-0142B	Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	Non-Fibrous Homogeneous		40% Non-fibrous (Other)	



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

		<u>Non-Asbestos</u>			<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
74-Drywall 12313753-0142C	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
175-Texture	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
No drywall present.					
175-White Coat	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		40% Quartz 15% Ca Carbonate 45% Non-fibrous (Other)	None Detected
175-Gray Coat 412313753-0143B	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	<1% Cellulose	60% Quartz 40% Non-fibrous (Other)	None Detected
176-Texture 412313753-0144	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
No drywall present.	110 00				
176-White Coat	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		40% Quartz 15% Ca Carbonate 45% Non-fibrous (Other)	None Detected
176-Gray Coat 412313753-0144B	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	<1% Cellulose	60% Quartz 40% Non-fibrous (Other)	None Detected
177-Texture 412313753-0145	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		75% Ca Carbonate 5% Perlite 20% Non-fibrous (Other)	None Detected
177-White Coat 412313753-0145A	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		40% Quartz 15% Ca Carbonate 45% Non-fibrous (Other)	None Detected
177-Gray Coat 412313753-0145B	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	<1% Cellulose	60% Quartz 40% Non-fibrous (Other)	None Detected
177-Drywall 412313753-0145C	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

			Non-Asbe	<u>Asbestos</u>	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
178-Texture	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		30% Ca Carbonate 70% Non-fibrous (Other)	None Detected
178-White Coat	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/	White Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
178-Gray Coat 412313753-0146B	No JC Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	<1% Cellulose <1% Hair	30% Quartz 70% Non-fibrous (Other)	None Detected
178-Drywall 412313753-0146C	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
179-Texture 412313753-0147	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		30% Ca Carbonate 70% Non-fibrous (Other)	None Detected
No drywall present,					
179-White Coat	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
179-Gray Coat 412313753-0147B	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous		30% Quartz 70% Non-fibrous (Other)	None Detected
180-Texture 412313753-0148	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
180-White Coat	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	White Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
180-Gray Coat 412313753-0148B	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	<1% Cellulose	30% Quartz 70% Non-fibrous (Other)	None Detected
180-Drywall 412313753-0148C	Build 6 - C & D Ceilings & Entry Stairs Walls - Text. Plaster & Drywall w/ No JC	Gray Non-Fibrous Homogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected
181-Tape	Laundry Shed - Drywall & JC	Yellow Fibrous Homogeneous	99% Glass	1% Non-fibrous (Other)	None Detected



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbes % Fibrous	stos % Non-Fibrous	<u>Asbestos</u> % Type
81-Joint Compound	Laundry Shed -	White	70 1 151 0 40	80% Ca Carbonate	None Detected
12313753-0149A	Drywall & JC	Non-Fibrous Homogeneous		20% Non-fibrous (Other)	None Detected
81-Drywall	Laundry Shed - Drywall & JC	White Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
112313753-0149B		Homogeneous			
82-Tape	Laundry Shed - Drywall & JC	Yellow Fibrous	99% Glass	1% Non-fibrous (Other)	None Detected
12313753-0150		Homogeneous			
82-Joint Compound	Laundry Shed - Drywall & JC	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
12313753-0150A		Homogeneous			
82-Drywall	Laundry Shed - Drywall & JC	White Non-Fibrous	5% Cellulose	95% Non-fibrous (Other)	None Detected
112313753-0150B		Homogeneous			
183-Tape	Laundry Shed - Drywall & JC	Yellow Fibrous	99% Glass	1% Non-fibrous (Other)	None Detected
112313753-0151	Lauradau Obi i d	Homogeneous		000/ 0- 0-1	Nama District
183-Joint Compound	Laundry Shed - Drywall & JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
	Loundry Chad	White	100/ Callulana	000/ Non fibrary (Other)	None Detected
83-Drywall 12313753-0151B	Laundry Shed - Drywall & JC	Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
	l averder Chard	Homogeneous	000/ 01	40/ Nov. Element (Othern)	Nama Data ata d
84-Tape 12313753-0152	Laundry Shed - Drywall & JC	Yellow Fibrous Homogeneous	99% Glass	1% Non-fibrous (Other)	None Detected
	Launder Chad	-		200/ Co Carbonata	None Detected
84-Joint Compound 12313753-0152A	Laundry Shed - Drywall & JC	White Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
	Laundry Shed -	White	10% Cellulose	90% Non-fibrous (Other)	None Detected
84-Drywall 12313753-0152B	Drywall & JC	Non-Fibrous Homogeneous	10 % Cellulose	90 % Non-librous (Other)	None Detected
185-Tape	Laundry Shed -	Yellow	99% Glass	1% Non-fibrous (Other)	None Detected
12313753-0153	Drywall & JC	Fibrous Homogeneous	oo w class	The Hell librous (Guist)	None Beleeted
185-Joint Compound	Laundry Shed -	White		80% Ca Carbonate	None Detected
12313753-0153A	Drywall & JC	Non-Fibrous Homogeneous		20% Non-fibrous (Other)	
85-Drywall	Laundry Shed - Drywall & JC	White Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
12313753-0153B		Homogeneous			
86-Tape	Laundry Shed - Drywall & JC	Yellow Fibrous	99% Glass	1% Non-fibrous (Other)	None Detected
12313753-0154	·	Homogeneous			
86-Joint Compound	Laundry Shed - Drywall & JC	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
112313753-0154A		Homogeneous			
86-Drywall	Laundry Shed - Drywall & JC	White Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
12313753-0154B		Homogeneous			
87-Tape	Laundry Shed - Drywall & JC	Yellow Fibrous	99% Glass	1% Non-fibrous (Other)	None Detected
112313753-0155		Homogeneous			
187-Joint Compound	Laundry Shed - Drywall & JC	White Non-Fibrous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
412313753-0155A		Homogeneous			



Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

		Non-Asbestos			<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
187-Drywall	Laundry Shed - Drywall & JC	White Non-Fibrous	10% Cellulose	90% Non-fibrous (Other)	None Detected
412313753-0155B	•	Homogeneous			

Analyst(s)

Ashley Hill (159) Kelsie Dwyer (41) Maggie Pasour (65) Matthew Schaefer (148) Lee Plumley, Laboratory Manager or Other Approved Signatory

Evan L Plumber

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC NVLAP Lab Code 200841-0, VA 3333 00312



Customer PO: Project ID:

Attention: Ted Shultz Phone: (803) 348-4921

Apex Environmental Management Fax:

7 Winchester Court Received Date: 11/16/2023 9:20 AM

Mauldin, SC 29662 Analysis Date: 11/24/2023 Collected Date: 11/14/2023

Project: CHA ACM Cola Apts

Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID	Description	Appearance	% Matrix Material	% Non-Asbestos Fibers	Asbestos Types
3-Shingle 412313753-0156	Build. 1 - Roof - 1 Shingle, 4 Felt	Gray/Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
3-Black Felt 1 412313753-0157	Build. 1 - Roof - 1 Shingle, 4 Felt	Black Fibrous Homogeneous	100.0 Other	None	<0.1% Chrysotile
3-Black Felt 2 412313753-0158	Build. 1 - Roof - 1 Shingle, 4 Felt	Black Fibrous Homogeneous	100.0 Other	None	<0.1% Chrysotile
3-Tan Felt 412313753-0159	Build. 1 - Roof - 1 Shingle, 4 Felt	Tan Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
3-Black Felt 3 412313753-0160	Build. 1 - Roof - 1 Shingle, 4 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
6 412313753-0161	Build. 1 - Exterior - Door & Window Caulk	White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
9-Tan Mastic/Leveler 412313753-0162	Build. 1 - B-Kitchen & Bath - Tan Textured Flooring & Yellow Mastic	Tan Non-Fibrous Heterogeneous	100.0 Other	None	No Asbestos Detected
9-Flooring 412313753-0163	Build. 1 - B-Kitchen & Bath - Tan Textured Flooring & Yellow Mastic	Gray/Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
9-Yellow Mastic 412313753-0164	Build. 1 - B-Kitchen & Bath - Tan Textured Flooring & Yellow Mastic	Yellow Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
12-Flooring 412313753-0165	Building 1 - C HVAC Closet - Grey Flooring w/ Mastic	Tan Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
12-Mastic 412313753-0166	Building 1 - C HVAC Closet - Grey Flooring w/ Mastic	Tan/White/Yellow Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
15-Flooring 412313753-0167	Building 1 - B Kitchen - Brown Marble Pattern Flooring w/ Mastic	Brown/Tan Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or < 1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC



Customer PO: Project ID:

Attention: Ted Shultz Phone: (803) 348-4921

Apex Environmental Management Fax:

7 Winchester Court Received Date: 11/16/2023 9:20 AM

Mauldin, SC 29662 Analysis Date: 11/24/2023 Collected Date: 11/14/2023

Project: CHA ACM Cola Apts

Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID	Description	Appearance	% Matrix Material	% Non-Asbestos Fibers	Asbestos Types
15-Mastic/Leveler 412313753-0168	Building 1 - B Kitchen - Brown Marble Pattern Flooring w/ Mastic	White Fibrous Heterogeneous	100.0 Other	None	No Asbestos Detected
18-Mastic 412313753-0169	Building 1 - A, B, C, D Bathroom - Tub Surround Mastic	Tan/Yellow Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
21 412313753-0170	Building 1 - Entry Stairwell - Stair Tread Mastic	Brown/Beige Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
38 412313753-0171	Build. 2 - Exterior - Door & Window Caulk	Gray/White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
41-Shingle 412313753-0172	Build. 2 - Roof - 1 Shingle, 3 Felt	Gray/Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
41-Felt 1 412313753-0173	Build. 2 - Roof - 1 Shingle, 3 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
41-Felt 2 412313753-0174	Build. 2 - Roof - 1 Shingle, 3 Felt	Black Fibrous Homogeneous	100.0 Other	None	<0.1% Chrysotile
41-Felt 3 412313753-0175	Build. 2 - Roof - 1 Shingle, 3 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
44 412313753-0176	Build. 2 - Entry Stairs - Stair Tread Mastic	Brown/Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
47-Flooring 412313753-0177	Build. 2 - E & F Kitchen - Grey Text Floor w/ Mastic	Brown/Gray/Tan Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
47-Mastic/Leveler 412313753-0178	Build. 2 - E & F Kitchen - Grey Text Floor w/ Mastic	Tan Non-Fibrous Heterogeneous	100.0 Other	None	No Asbestos Detected
50-Flooring 412313753-0179	Build. 2 - G & H Kit & Bath - Grey Text Floor w/ Mastic	Tan/Beige Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or <1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC



Customer PO: Project ID:

Attention: Ted Shultz Phone: (803) 348-4921

Apex Environmental Management Fax:

7 Winchester Court Received Date: 11/16/2023 9:20 AM

Mauldin, SC 29662 Analysis Date: 11/24/2023 Collected Date: 11/14/2023

Project: CHA ACM Cola Apts

Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID	Description	Appearance	% Matrix Material	% Non-Asbestos Fibers	Asbestos Types
50-Mastic 412313753-0180	Build. 2 - G & H Kit & Bath - Grey Text Floor w/ Mastic	Yellow Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
67-Shingle 412313753-0181	Build 3 - Roof - 1 Shingle, 3 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
67-Felt 1 412313753-0182	Build 3 - Roof - 1 Shingle, 3 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
67-Felt 2 412313753-0183	Build 3 - Roof - 1 Shingle, 3 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
67-Felt 3 412313753-0184	Build 3 - Roof - 1 Shingle, 3 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
70 412313753-0185	Build 3 - Exterior - Door & Window Caulk	White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
73 412313753-0186	Build 3 - Entry Stairs - Stair Tread Mastic	Brown/Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
76 412313753-0187	Build 3 - I, J, K, L Bathrooms - Tub Surround Mastic Only	Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
79-Gray Flooring 412313753-0188	Build 3 - K & L Bathroom Floor, 2 Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Gray Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
79-Mastic 412313753-0189	Build 3 - K & L Bathroom Floor, 2 Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Beige Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
79-Tan Flooring 412313753-0190	Build 3 - K & L Bathroom Floor, 2 Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Tan Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
79-Mastic/Leveler 412313753-0191	Build 3 - K & L Bathroom Floor, 2 Layers - Grey Floor w/ Mastic Tanish Floor w/ Mastic	Brown/Yellow Non-Fibrous Heterogeneous	100.0 Other	None	No Asbestos Detected

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or <1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC



Customer PO: Project ID:

Attention: Ted Shultz Phone: (803) 348-4921

Apex Environmental Management Fax:

7 Winchester Court Received Date: 11/16/2023 9:20 AM

Mauldin, SC 29662 Analysis Date: 11/24/2023 Collected Date: 11/14/2023

Project: CHA ACM Cola Apts

Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID	Description	Appearance	% Matrix Material	% Non-Asbestos Fibers	Asbestos Types
82-Flooring 412313753-0192	Build 3 - I & J Kit Floor - Marble Pat Floor & Mastic	Tan Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
82-Mastic/Leveler 412313753-0193	Build 3 - I & J Kit Floor - Marble Pat Floor & Mastic	Tan/Yellow Non-Fibrous Heterogeneous	100.0 Other	None	No Asbestos Detected
99-Shingle 412313753-0194	Build 4 - Roof - 1 Shingle, 1 Felt	Gray/Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
99-Felt 412313753-0195	Build 4 - Roof - 1 Shingle, 1 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
102 412313753-0196	Build 4 - Exterior - Door & Window Caulk	White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
105 412313753-0197	Build 4 - ABCD Entry Stairs - Stair Tread Mastic	Brown/Beige Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
108-Mastic 412313753-0198	Build 4 - ABCD Bathrm - Tub Surround Mastic	Tan/Yellow Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
111-Vinyl 412313753-0199	Build 4 - ABCD Kit & Bath - Marble Pat Vinyl w/ Mastic	Brown/Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
111-Mastic 412313753-0200	Build 4 - ABCD Kit & Bath - Marble Pat Vinyl w/ Mastic				
Insufficie	nt Material				
128-Shingle 412313753-0201	Build 5 - Roof - 1 Shingle, 3 Felt	Gray/Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
128-Felt 1 412313753-0202	Build 5 - Roof - 1 Shingle, 3 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
128-Felt 2 412313753-0203	Build 5 - Roof - 1 Shingle, 3 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or <1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC



Customer PO: Project ID:

Attention: Ted Shultz Phone: (803) 348-4921

Apex Environmental Management Fax:

7 Winchester Court Received Date: 11/16/2023 9:20 AM

Mauldin, SC 29662 Analysis Date: 11/24/2023 Collected Date: 11/14/2023

Project: CHA ACM Cola Apts

Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID	Description	Appearance	% Matrix Material	% Non-Asbestos Fibers	Asbestos Types
128-Felt 3 412313753-0204	Build 5 - Roof - 1 Shingle, 3 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
131 412313753-0205	Build 5 - Exterior - Door & Window Caulk	White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
134 412313753-0206	Build 5 - Entryway Stairs - Stair Tread Mastic	Brown/Beige Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
137 412313753-0207	Build 5 - EFGH Bathrm - Tub Surround Mastic Only	Tan/Yellow Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
140-Flooring 412313753-0208	Build 5 - EFGH Kitchen & Bath - Marble Text Floor & Mastic	Brown/Tan Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
140-Mastic 412313753-0209	Build 5 - EFGH Kitchen & Bath - Marble Text Floor & Mastic				
Insuffici	ent Material				
157-Shingle 412313753-0210	Build 6 - Roof - 1 Shingle, 2 Felt	Gray/Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
157-Felt 1 412313753-0211	Build 6 - Roof - 1 Shingle, 2 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
157-Felt 2 412313753-0212	Build 6 - Roof - 1 Shingle, 2 Felt	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
160 412313753-0213	Build 6 - Exterior - Door & Window Caulk	Gray Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
163 412313753-0214	Build 6 - Entry Stairs - Stair Tread Mastic	Brown/Beige Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
166-Flooring 412313753-0215	Build 6 - ABCD Kitchens - Marble Text Pat Flr w/ Mastic	Tan/White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or < 1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC



Customer PO: Project ID:

Fax:

Attention: Ted Shultz Phone: (803) 348-4921

Apex Environmental Management

7 Winchester Court Received Date: 11/16/2023 9:20 AM

Mauldin, SC 29662 Analysis Date: 11/24/2023 Collected Date: 11/14/2023

Project: CHA ACM Cola Apts

Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID
Description
Appearance
% Matrix Material
% Non-Asbestos Fibers
Asbestos Types

166-Mastic
412313753-0216
Marble Text Pat Fir w/
Mastic
Insufficient Material

Analyst(s)

Maggie Pasour (58)

Lee Plumley, Laboratory Manager or other approved signatory

Evan L Plumber

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or <1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC

Asbestos Bulk Building Materials - Chain of Custody 10801 Southern Loop Blvd

LIVIUE Analytical, IIIC.

EMSL ANALYTICAL, INC.

EMSL Order Number / Lab Use Only

Pineville, NC 28134

PHONE:	(704) 525-2205

EMAIL: charlottelab@EMSL.com Billing ID: Customer ID: Information Company Name: Apex Environmental Management Company Name Apex Environmental Management Information Billing Contact: Contact Name: Rebecca Shultz Ted Shultz Street Address: 7 Winchester Court Street Address: 7 Winchester Court Customer Country: US City, State, Zip: 29662 Country: US Billing City, State, Zip. Mauldin Mauldin SC SC Phone. Phone: 864-404-3210 864-404-3210 Email(s) for Invoice: Email(s) for Report: tshultz@apex-ehs.com **Project Information** Project CHA ACM Cola Apts Order. Name/No State of Connecticut (CT) must select project location: EMSL LIMS Project ID: (if applicable, EMSL will provide) US State where SC samples collected: Residential (Non-Taxable) Commercial (Taxable) Sampled By Name: No. of Samples In Shipment 3 Hour 24 Hour 32 Hour 48 Hour 96 Hour *32 Hour TAT av Test Selection TEM - Bulk PLM - Bulk (reporting limit) TÉM EPA NOB PLM EPA 600/R-93/116 (<1%) NYS NOB 198.4 (Non-Friable - NY) PLM EPA NOB (<1%) TEM EPA 600/R-93/116 w Milling Prep (0.1%) POINT COUNT 400 (<0.25%) 1,000 (<0.1%) POINT COUNT W/ GRAVIMETRIC Other Tests (please specify) 400 (<0.25%) 1,000 (<0.1%) NIOSH 9002 (<1%) NYS 198,1 (Friable - NY) NYS 198,6 NOB (Non-Friable - NY) NYS 198.8 (Vermiculite SM-V) Positive Stop - Clearly Identified Homogeneous Areas (HA) H Sample Number **HA Number** Sample Location **Material Description** door + window caulk B-Kitchen + Ba-Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.) Sample Condition pop Receipt: Method of Shipment Relinquished by 920A Relinquished by Date/Time Received by: Date/Time AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.

OrderID: 412313753 EMSL Analytical, Inc. Asbestos Bulk Building Materials - Chain of Custody 10801 Southern Loop Blvd Pineville, NC 28134 EMSL ANALYTICAL, INC. 4 13753 PHONE: (704) 525-2205 EMAIL: charlottelab@EMSL,com Additional Pages of the Chain of Custody are only necessary if needed for additional sample information Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.) Sample Number **HA Number** Sample Location **Material Description** HUAC CLOSEF Kitchen fooring w/ mastic ABOD BOTH ACOM masfic entry stair well walls + Ceiling Stair well walls + dry wall w/ Method of Shipment: Sample Condition Upon Receipt: Relinquished by: Date/Time: Received by: Date/Time Relinquished by. Date/Time: Received by: Date/Time Controlled Document - Asbestos Bulk R7 09/14/2021 AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.

16.

OrderID: 412313753 EMSL Analytical, Inc. Asbestos Bulk Building Materials - Chain of Custody 10801 Southern Loop Blvd ÉMEI EMSL Order Number / Lab Use Only Pineville, NC 28134 EMSL ANALYTICAL, INC. 13753 PHONE: (704) 525-2205 EMAIL: charlottelab@EMSL.com Additional Pages of the Chain of Custody are only necessary if needed for additional sample Information

| Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.) **HA Number** Sample Number **Material Description** * entry stainmell walls 70 DC Build I text plasfor + dry val EJF Kitchen ſ E.F.G.H walls + ceiling Method of Shipment: Sample Condition Upon Receipt: Relinquished by: Received by: Date/Time: Date/Time Date/Time: Relinquished by: Received by: Date/Time Controlled Document - Asbestos Bulk R7 09/14/2021 AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.) EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc.

of

OrderID: 412313753 EMSL Analytical, Inc. Asbestos Bulk Building Materials - Chain of Custody 10801 Southern Loop Blvd **€MS** EMSL Order Number / Lab Use Only Pineville, NC 28134 EMSL ANALYTICAL, INC. 13753 PHONE: (704) 525-2205 EMAIL: charlottelab@EMSL.co Additional Pages of the Chain of Custody are only necessary if needed for additional sample Information

Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.) Sample Number **HA Number** Material Description Sample Location Build 2 Build 3 Ishingle, 3 fel char & window Extegion caulk 11 Entry stairs KL Bath rooms ROOM Floor grey floor w/ nastic Method of Shipment: Sample Condition Upon Receipt: Relinquished by: Date/Time: Received by: Date/Time Relinquished by: Date/Time: Received by: Date/Time

Controlled Document - Asbestos Bulk R7 09/14/2021

AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

OrderID: 412313753 EMSL Analytical, Inc. Asbestos Bulk Building Materials - Chain of Custody 10801 Southern Loop Blvd **EMS** EMSL Order Number / Lab Use Only Pineville, NC 28134 EMSL ANALYTICAL, INC. 13753 PHONE: (704) 525-2205 EMAIL: charlottelab@EMSL.com Additional Pages of the Chain of Custody are only necessary if needed for additional sample information Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.) **HA Number** Sample Location Material Description Sample Number I, J, K, L walls + ceiling Build 3 entry stairs walls + drywall w/ no **)** [. Build 4 1 Shingle, 1 fe 1:4 ROOF 99 Exterior 00 Cutry stairs Method of Shipment: Sample Condition Upon Receipt: Relinquished by: Date/Time: Received by: Date/Time Relinquished by: Date/Time: Received by: Date/Time Controlled Document - Asbestos Bulk R7 09/14/2021 AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

9

OrderID: 412313753 EMSL ANALYTICAL, INC.

Asbestos Bulk Building Materials - Chain of Custody 10801 Southern Loop Blvd

EMSL Analytical, Inc.

13753

Pineville, NC 28134 PHONE: (704) 525-2205

EMAIL: charlottelab@EMSL.com

Additional Pages of the Chain of Custon	dy are only necessary if needed for a Special instructions a	dditional sample information nd/or Regulatory Requirements (Sample Specia	fications, Processing Methods, Limits of	Detection, etc.)
	opeda monocoro	mad riegolotory riedolomiemo (estripio apoe		
				{
Sample Number	HA Number	Sample I	ocation.	Material Description
106	Build 4	ARAD B	athem	Tub surround
107				wastic
108				+
109		ABOD Kit	4 Bath	madale pat.
110		1		Viny/ w/masti
(1)				, , ,
1/2		ABOB Wall	5 + ceiling	drywall &
113			7	Jc
s)2/				
1/5		77	A. Say	
116		·	· ,	
117				
118				
119		C+D ceilin	igs upstairs	text plaster + dryvall wind to
120			7	dryvall wind Jo
121				
122				
193	·			
124				
125				
126	Builds	5 Roof		1 shingle, is felt
127				
128		1	·	
B				
		<u> </u>		
Method of Shipment:			Sample Condition Upon Receipt	Interest
Relinquished by:			Received by:	Date/Time
Relinquished by: Controlled Document - Asbestos Bulk R7	DE114/2023	Date/Time:	Received by:	Date/Time
Computed Proceduratin - Wagestod Brity KV		ETO ELECTRONIC SIGNATURE (By checking, I	consent to signing this Chain of Custody d	locument by electronic signature.)

9

Asbestos Bulk Building Materials - Chain of Custody 10801 Southern Loop Blvd

EMSL Order Number / Lab Use Only

EMSL Analytical, Inc.

13753

Pineville, NC 28134 PHONE: (704) 525-2205

EMAIL: charlottelab@EMSL.com Additional Pages of the Chain of Custody are only necessary if needed for additional sample Information

Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.) Sample Number **HA Number** Sample Location **Material Description** Build S Entry way stairs EFGH Bath RIN mastic only EFGH Kitchen & Bath EFGH ceiling + walls drywall thus GAH entry stairs teeiling text. plaster

+ drywall w/no Method of Shipment Sample Condition Upon Receipt: Relinquished by: Date/Time: Received by: Date/Time Relinquished by: Date/Time: Received by: Date/Time Controlled Document - Asbestes Bulk R7 09/14/2021

9

AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

rolled Document - Asbestos Bulk R7 09/14/2021

Asbestos Bulk Building Materials - Chain of Custody 10801 Southern Loop Blvd EMSL Order Number/ Lab Use Only

EMSL Analytical, Inc.

7.7

13755

Pineville, NC 28134 PHONE: (704) 525-2205

EMSL ANALYTICAL, INC. EMAIL: charlottelab@EMSL.com Additional Pages of the Chain of Custody are only necessary if needed for additional sample information Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.) **HA Number Material Description** Sample Number Sample Location 1 shinge, 27 Entry Stairs Kitchens ABCD walls + oriling drywall & Ja Method of Shipmen Sample Condition Upon Receipt Received by: Relinquished by: Date/Time: Date/Time Relinquished by: Date/Time: Received by: Date/Time

9

AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

OrderID: 41<u>2313</u>753 EMSL ANALYTICAL, INC.

Asbestos Bulk Building Materials - Chain of Custody 10801 Southern Loop Blvd EMSL Order Number / Lab Use Only

EMSL Analytical, Inc.

13753

Pineville, NC 28134 PHONE: (704) 525-2205

Controlled Document - Asbestos Bulk R7 0		E TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody	
Relinquished by:		Date/Time: Received by:	Date/Time
Relinquished by:		Date/Time: Received by:	Date/Time
Method of Shipment:		Sample Condition Upon Receipt	
		 	
	<u>-</u>		
			
			
			<u> </u>
·	<u> </u>		
			<u> </u>
			
			
			
			
167			
186			
185			
184			
183			
182			· · · · · ·
181	Laurdey S	sed drywall & Je	
Sample Number			Material Description
	HA Number	Sample Location	Material Description

9

APPENDIX III PHOTOGRAPHS



Photo 1 – Front view Columbia Apartments.





Photo 2 – Holes cut through roofs prior to survey.



Photo 3 – Typical front view of Apartments.



Photo 4 – Typical view of rear of apartments.



Photo 5 – Typical view of window caulk.



Photo 6 – Typical view of Kitchen flooring.



Photo 7 – Typical view of collapsed ceiling and hardwood floors.



Photo 8 – Typical view of the collapsed ceiling.



Photo 9 – Typical view of tub surround.



Photo 10 – Typical view of vinyl bathroom flooring.



Photo 11 – Typical view of tub surround mastic.



Photo 12 – Collapsed ceiling due to roof holes.



Photo 13 – Entry stair well with plaster and stair tread.



Photo 14 – Upstairs ceiling texture.



Photo 15 – Typical view of vinyl flooring in HVAC closets.



Photo 16 – Two layers of bathroom vinyl flooring.



Photo 17 - Roof shingles and felt.



Photo 18 – Laundry shed.

Apex Project # 1123-202 Columbia Apartments Asbestos Assessment Columbia, South Carolina December 19, 2023



Photo 19 – Laundry shed drywall with concrete slab.